

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐  
2. NAME OF OPERATOR  
Ray Westall  
3. ADDRESS OF OPERATOR  
Box 4 Loco Hills, NM 88255  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL & 610' FWL  
AT TOP PROD. INTERVAL: same  
AT TOTAL DEPTH: same

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
CHANGE ZONES ☐  
ABANDON\* ☐

SUBSEQUENT REPORT OF:

(other) Spud, 13 3/8", 8 5/8", T.D., 5 1/2"

RECEIVED BY  
JUN 26 1986  
O. C. D.  
ARTESIA, OFFICE

5. LEASE  
NM-27278  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
Featherstone Federal  
9. WELL NO.  
2  
10. FIELD OR WILDCAT NAME  
Und. Shugart - y - SE - Q - G  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Sec. 26. T18S R30E  
12. COUNTY OR PARISH  
Eddy  
13. STATE  
NM  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3406. GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

06-06-86 Spud 17 1/2" hole @ 8:30 A.M. Ran 14 jts. 575' of 13 3/8" csg. Cemented @ 572' w/500 sxs Hi-early 2, 2% CC, 1/4# Cello-flake per sk. Plug down @ 9:00 P.M. Circulated 75 sxs to pits. WOC 18 hrs. Changed to 12 1/4" bit.

06-09-86 Ran 54 jts. 24# J55 8 5/8" csg. (1692') Set & cemented @ 1710' w/675 sxs DLW 5 Std w/3# D-44 per sk, 4% gel-tail w/200 sxs HE-2 2% CC, plug down @ 6:15 P.M. Circulated 123 sxs to pits. WOC 18 hrs. Pressured up to 1000# for 30 min. Held O.K.

06-12-86 T.D. @ 3500'. Ran 110 jts. (3510') 5 1/2" csg. Set & cemented @ 3500' w/150 sxs Dowell liteweight 3-5 (5#/sk salt, 2% D-46) 300 sxs tail-in standard (3# sk salt, 5% 059, 2% D-46) Plug down @ 6:40 A.M. 6-13-86 WOC 24 hrs.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Ray Westall TITLE Operator DATE 6-18-86

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

GWD

JUN 23 1986

\*See Instructions on Reverse Side