

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYForm approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 42410

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Comstock Federal

9. WELL NO.

8

10. FIELD AND POOL, OR WILDCAT

Artesia On-GB-SA

11. SEC. T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 12-18S-27E

12. COUNTY OR PARISH

Eddy

13. STATE

NM

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☒ GAS WELL ☐ OTHER Dry

2. NAME OF OPERATOR

Fred Pool Drilling, Inc.

3. ADDRESS OF OPERATOR

P.O. Box 1393 Roswell, N.M. 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State regulations.  
See also space 17 below.)  
At surface

1650 FSL 990 FWL

14. PERMIT NO.

30 015 25649

15. ELEVATIONS (Show whether DF, ST, GR, or C. D.)

3579'

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐  
☐  
☐  
☐

PULL OR ALTER CASING

☐  
☐  
☐  
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON\*

REPAIR WELL

CHANGE PLANS

(Other)

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐  
☐  
☐  
☐

REPAIRING WELL

☐  
☐  
☐  
☒

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT\*

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

12-31-86: Ran tubing to 2000' and loaded hole with mud.  
Spotted 25 sx class C cement from 2000' to 1875'.  
Pulled 19 joints of tubing to 1398', spotted  
second plug from 1398' to 1273'.

Pulled out all tubing and pulled 7" Casing.

Ran 13 joints of tubing to 403' and spotted 50 sx  
cement plug across shoe of surface casing, pulled  
tubing and shut down.

1-1-87

Tagged 3rd plug at 273'.

Pulled tubing to 64' and spotted surface plug from  
64' to surface. P & A complete.

P & A witnessed by BLM representative Danny Cortez.

Intend to install dry hole marker and rehab location.

18. I hereby certify that the foregoing is true and correct

SIGNED

*Penta Pool*

TITLE Vice President

DATE 1-7-87

(This space for Federal or State office use)

APPROVED BY

Acting Area Manager

TITLE

DATE

1-13-87

CONDITIONS OF APPROVAL, IF ANY:

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

\*See Instructions on Reverse Side

Post ID-2  
1-30-87  
P & A