

30-015-25859  
clsf

Form 3160-5  
(June 1990)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

RECEIVED

OCT 29 12 30 PM '91

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

5. Lease Designation and Serial No.  
NM-64595

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.  
PBIC Federal #1

9. API Well No.

10. Field and Pool, or Exploratory Area  
North Shugart BS

11. County or Parish, State  
Eddy, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reenter a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

RECEIVED

MAR 13 1992

O. C. D.  
OFFICE

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
Manzano Oil Corporation ✓

3. Address and Telephone No.  
P.O. Box 2107, Roswell, NM 88201

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1780' FSL & 800' FWL  
Sec 7, T18S-R31E, NMPM

ut. w

12 CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
<input checked="" type="checkbox"/> Notice of Intent	<input checked="" type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Other _____	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Set Bull plug Loc - Set packer @ 7875' [Cap W/35' cement]
2. Set 25 sks cement plug from 7400'-7100' - sig
3. Set 25 sks cement plug from 3790'-3450' - sig
4. Pull and recover as much 5-1/2" casing as possible (top of cmt is 2590')
5. Set 25 sks cement plug @ 5-1/2" casing stub - sig
6. Set 25 sks cement plug at 8-5/8" casing shoe - sig
7. Set 10 sks surface plug.
8. Install dry hole marker.

7. Set 25 sks cement plug @ 13 3/8" casing shoe from 400-600'

Part FD-2  
5-29-92  
P+P

14. I hereby certify that the foregoing is true and correct

Signed Jana J. Jones  
(This space for Federal or State official use)

Title Production Analyst

Date 10/25/91

Approved by Ronald H. Glass  
Conditions of approval, if any:

Title \_\_\_\_\_

Date 3-12-92

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side