NM OIL CONS COMMITTE Drawer DD Artesia, NM 88210

Form 3160-5 (June 1990)

## UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT 5. Lease Designation and Serial No. NM42410 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals 7. If Unit or CA, Agreement Designation SUBMIT IN TRIPLICATE 1. Type of Well X Oil Well Gas Well 8. Well Name and No. Other 2. Name of Operator COMSTOCK FED. NO.10 9. API Well No. THE EASTLAND OIL COMPANY 3. Address and Telephone No. 30-015-26017 915/683-6293 10. Field and Pool, or Exploratory Area P. O. DRAWER 3488, MIDLAND, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) ARTESIA ON, GB, SA 11. County or Parish, State 990' FSL &1650' FWL, Sec. 12, T-18-S, R-27-E EDDY, NM Unit Letter N CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA 12 TYPE OF ACTION TYPE OF SUBMISSION Notice of Intent Abandonment Change of Plans Recompletion **New Construction** Subsequent Report Non-Routine Fracturing Plugging Back Water Shut-Off Casing Repair Conversion to Injection Final Abandonment Notice Altering Casing ☐ Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\* 1483'-92' T.D.-2040-PBTD-1998-Perfs: Casing in hole as follows: 8-5/8" 24# @351' cement circulated to surface 4-1/2" 9.5# @2039' cement circulated to surface Propose to plug as follows: 1) 25 sk class C w/2% CHCl @1492' in 4-1/2" csg & tag plug. 2) load hole w/mud laden fluid 3) spot 30 sk plug @655' across top of salt 4) spot 10 sk plug @surface 5) cut off heads & install 4" x 4' marker 6) restore location

OIL CON. DIV. DIST. 2

14. I hereby certify that the foregoing is true and correct		
Signed Asseris Reld	Title Production Superintendent	Date 2-8-95
(This space for Federal or State office use)		, ,
Approved by (ORIG. SGD.) JOE G. LARA Conditions of approval, ir and Dee attached. A  Cr CIBP above perfs wy	Title PETROLEUM ENGINEER	Date 3//3/95 S from 1438-1542'4 tag
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingl	35'cmt.	

## BUREAU OF LAND MANAGEMENT CARLSBAD RESOURCE AREA

## Permanent Abandonment of Wells on Federal Lands

## Conditions of Approval

- 1. <u>Approval:</u> Plugging operations shall commence within 90 days from the approval date of plugging procedure.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Eddy County call (505)887-6544; for wells in Lea County call (505) 393-3612.
- 3. <u>Blowout Preventers:</u> A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement:</u> Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C", for up to 7,500 feet of depth, mixed at 14.8 lbs./gal. with 6.3 gallons of fresh water per sack or class "H", for deeper than 7,500 feet plugs, mixed at 16.4 lbs./gal. with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. Show <u>date</u> well was plugged.

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval will be developed and furnished to you.