Form 3160-5 (November 1983) (Formerly 9-331)		UNIT O STATES MENT OF THE L MENAM DNAM TO UA	NTERIOR	(Other instructions	Budget Expires 5. LEASE DES LC-02941	· 	5 AL 80	
(Do not use	this form for propo	ICES AND REPORTED TO SERVICE AND REPORTED TO SERVICE TO	or plug back to	a different reservoir.	O. IS TABLES,	ALLOTTEE OR TRIBE		
OIL GAS OTHER Dry Hole				REGENTED		7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME		
BTA OIL PRODUCERS				4PR 26 '89		Puckett, 8809 JV-P		
104 South Pecos, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any Sta See also space 17 below.) At surface 2,310 FSL & 1,650 FWL				requirements. O.	Wildca	2 10. FIELD AND POOL, OR WILDCAT Wildcat 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA		
14. PERMIT NO.		15. ELEVATIONS (Show				T-17-S, R-		
30-015-260		3,864 GR	-		Eddy Other Deta	N.1	ـــــــ	
16.	Check A	•	dicate lyature	e of Notice, Report, or	EQUENT REPORT OF	':		
FRACTUBE TREAS SHOOT OF ACIDI REPAIR WELL (Other) 17. DESCRIBE PROPOS proposed wort nent to this we	ED OR COMPLETED OF	PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON® CHANGE PLANS ERATIONS (Cledity State a consily drilled, give subsu	Il pertinent deta	WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report results of the confidence of the confidenc	at AB	mpletion on Well od Log form.)	X ting any	
S F	Spotted P&A ? Plug #1: 75 Plug #2: 75	inished logging plugs as follow sx 8,100' - 7, sx 7,200' - 7, sx 5,200' - 5,	900 ' 000' WOC 4	hrs & tagged as	s required.			
I	Plug #5: 75 Plug #6: 75	sx 3,000' - 2,		hrs & tagged as	s required.	* 1		
<u> </u>	Well P&A 2:3	0 P.M. 4-11-89	Rig relea	ised: 6:00 P.M.	MORT	: 		
				Post : 4-28	7-89	* ***		
				P+	A	· · · · · · · · · · · · · · · · · · ·	Ċ	
18. I hereby certify	that the foreguing		rte Regula	tory Administrat	Or DATE	4/13/89		
APPROVED BY	Federal or State of	Show Fi	ok: C	+	DATE	4.25 1	<u> </u>	