

HALLIBURTON DIVISION LABORATORY

HALLIBURTON SERVICES

ARTESIA DISTRICT

LABORATORY REPORT

No. W342-93

TO Mvco Industries
105 South Fourth Street
Artesia, NM 88210

Date November 22, 1993

This report is the property of Halliburton Services and neither it nor any part thereof nor a copy thereof is to be published or disclosed without the written approval of laboratory management. It may however, be used in the course of regular business operations by any person or company and employees thereof receiving such report from Halliburton Services.

Submitted by Nelson Muncy Date Rec. _____Well No. East Turkey Track Fed. #1 Depth _____ Formation Penn

Field _____ County _____ Source _____

Resistivity09 @ 63°Specific Gravity .. 1.0675 @ 65°pH 6.5Calcium 2,000Magnesium 500Chlorides 58,000Sulfates 500Bicarbonates 150Soluble Iron 50

Remarks:

Art Carrasco
 Respectfully submitted

Analyst: Art Carrasco - Technical Advisor

HALLIBURTON SERVICES

NOTICE:

This report is for information only and the content is limited to the sample described. Halliburton makes no warranties, express or implied, as to the accuracy of the contents or results. Any user of this report agrees Halliburton shall not be liable for any loss or damage, regardless of cause, including any act or omission of Halliburton, resulting from the use hereof.