

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

1000 ns VISIO
1 st
lesia, NM 210-283

FORM APPROVED
Budget Bureau No. 1004-0135
Expires March 31, 1993

C/SF

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well
☐ Oil Well ☐ Gas Well ☒ Other WIW

2. Name of Operator
DEVON ENERGY CORPORATION (NEVADA)

3. Address and Telephone No.
20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
**990' FNL & 1700' EEC, Section 8-18S-27E
FWL**

5. Lease Designation and Serial No. NM-7713
6. If Indian, Allottee or Tribe Name
7. If Unit or CA, Agreement Designation West Red Lake Unit 8910089700
8. Well Name and No. West Red Lake Unit #50
9. API Well No. 30-015-26428
10. Field and Pool, or Exploratory Area Red Lake (Q-GB-SA)
11. County or Parish, State Eddy County, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	
☐ Notice of Intent	☐ Abandonment	☐ Change of Plans
☒ Subsequent Report	☐ Recompletion	☐ New Construction
☐ Final Abandonment Notice	☐ Plugging Back	☐ Non-Routine Fracturing
	☐ Casing Repair	☐ Water Shut-Off
	☐ Altering Casing	☒ Conversion to Injection
	☐ Other _____	☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Permit # WFX 719

Existing Perfs: 1644'-1928' San Andres
New Perfs: 1190'-1556' San Andres

Acidize San Andres perfs @ 1644'-1928' w/400 gals xylene + 4,000 gals 15% NE-FE acid in four stages using 80 BS's TIH w/ 3 1/8" csg gun & perforate the San Andres w/ JSPF @ 1190', 91', 92', 93', 94', 1213', 14', 15', 24', 25', 26', 1300', 01', 02', 28', 46', 55', 62', 68', 76', 80', 89', 98', 1500', 02', 04', 06', 22', 28', 30', 32', 36', 38', 54', & 56' for a total of 36 holes. TIH w/treating pkr & RBP on 2 3/8" tbg & set RBP @ $\pm$ 1600'. Release pkr, spot acid across perfs & reset @ $\pm$ 1100'. Acidize San Andres perfs @ 1190'-1556' w/a total of 5,000 gals 15% NE-FE acid spacing 72 BS's. Release pkr, retrieve RBP, TOH & LD 2 3/8" tbg & pkr & RBP. PU nickel plated Baker J-Lok pkr, 2 3/8" 4.7# J-55 8RD EUE IPC tbg, set pkr @ 1115', Ran MIT test 300 psi/15 min

Ready for injection 8-6

14. I hereby certify that the foregoing is true and correct

Signed Crystal Thornton

Crystal Thornton
Title Engineering Technician

Date August 19, 1997

(This space for Federal or State office use)

Approved by _____
Conditions of approval, if any:

Title _____

Date _____

ACCEPTED FOR RECORD
AUG 20 1997
BLM

RECEIVED
AUG 25 P 11:30
BUREAU OF LAND MANAGEMENT
ROSWELL OFFICE

Part ID-3
9-19-97
Prod to WTW

P.K.