

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Budget Bureau No. 1004-0135

Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO. *dsf*

NM-86107

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Kaiser Lake Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Lake East Morrow

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 32-T18S-R27E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

AUG 02 1991

O. C. D.
ARTESIA, OFFICE

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Mewbourne Oil Company

3. ADDRESS OF OPERATOR

P.O. Box 5260 Hobbs, New Mexico 88241

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Surface: 1650' FSL & 1650' FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3287.2 G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other)

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) Change of Plans

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

X

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

T.D. 12-1/4" Intermediate hole @ 4502'. Trip out of hole to run 8-5/8" Intermediate casing. Drill collars stuck @ 1175'-1205' with bit @ 1790'. Unable to get drill collars loose. Left 6" and 8" drill collars + 12-1/4" bit in the hole. Spotted 150' Class "C" cement plug on top of fish @ 1175'. Will redrill 12-1/4" Intermediate hole from 1000' to 4500'. Received verbal approval for the above operation from Adam M. Salameh, P.E.; Bureau of Land Management office in Carlsbad on July 25, 1991.

18. I hereby certify that the foregoing is true and correct

SIGNED W.H. Cravy

TITLE District Supt.

DATE July 26, 1991

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

