Form 3160-5 (June 1990)

CONDITIONS OF APPROVAL, IF ANY:

representations as to any matter within its jurisdiction.

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

## NM OIL CONS COMMISSION Drawer DD Artesia, NM 88210 Artesia, NM APPROVED

C/5/

Budget Bureau No. 1004-0135

SUNDRY NOTICES AND REPORTS ON WELLS  Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.		Expires: March 31, 1993
		5. Lease Designation and Serial No.
		LC-029420-B
Use "APPLICATION	FOR PERMIT" for such proposals	6. If Indian, Alottee or Tribe Name
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well: OIL GAS WELL WELL	OTHER	8. Well Name and Number
2. Name of Operator	— OTHER	DOW "B" 33 FEDERAL
TEXACO EXPLOR	RATION & PRODUCTION INC.	1
3. Address and Telephone No. P.O. BOX 730, HOBBS, NM 88240 397-0418		9. API Well No. 30-015-27068
4. Location of Well (Footage, Sec., T., R., M., or Surve	ey Description)	10. Field and Pool, Exploratory Area
Unit Letter J: 2180 Feet From 1	The SOUTH Line and 1980 Feet From T	
EAST Line Section 33	Township 17S Range 31E	11. County or Parish, State
Line Section 33	Township 17S Range 31E	EDDY , NEW MEXICO
Check Appropriate	Box(s) To Indicate Nature of Notice	e, Report, or Other Data
TYPE OF SUBMISSION		TYPE OF ACTION
	Abandonment	Change of Plans
N	Recompletion	New Construction
Notice of Intent	⊠ Plugging Back	Non-Routine Fracturing
Subsequent Report	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	OTHER:	Dispose Water
		(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)
directionally drilled, give subsurface locations and	measured and true vertical depths for all markers and zo	
BY THIS NOTICE OF INTENT, TEPI PROPOS THE WILDCAT GRAYBURG.	ES TO PLUG BACK & RECOMPLETE THIS WEL	LL FROM THE EDDY UNDESIGNATED GROUP 5 TO
<ol> <li>TIH W/ 5 1/2" CIBP &amp; SET @ +/- 8000'. DU</li> <li>TIH W/ 2 7/8" TBG TO 3800'. LOAD HOLE</li> <li>RU WIRELINE W/ PACKOFF. TIH W/ GR-TOH W/ LOGGING EQUIPMENT.</li> <li>TIH W/ 4" CSG GUN W/ 120 DEG SPIRAL INTERVAL: 3688' - 3726' (26' NET, 104 HO</li> </ol>	RAM BOP W/ 2 7/8" PIPE RAMS IN BOTTOM. MP 35' CMT ON TOP W/ BAILER (PROPOSED F W/ 2% KCL. CLOSE PIPE RAMS & TEST CIBP 8 CCL-CBL & LOG FROM 4000'-3000'. HOLD 1000 PHASING, 4 JSPF & PERFORATE THE FOLLOW PLES). 7/8" TBG. TEST TBG INTO HOLE TO 5000#. SE	& CSG TO 3000#. TOH W/ TBG. DPSI ON CSG WHILE LOGGING. VING GRAYBURG SAND
BACKSIDE & TEST PKR TO 500#. ND BO	P, NU 5000# FRAC TREE. RU FLOWBACK LINE	ES OFF ADJUSTABLE CHOR E CEIVE
PUMP @ AN AVERAGE RATE OF 7 - 8 BP MONITOR DURING JOB. FLUSH TO BOT	G PERFS 3688'-3726' W/ 3000 GALLONS 15% N M W/ MAX PRESSURE NOT TO EXCEED 5000#. TOM PERF W/ 2% KCL WATER. SD, GET ISIP, ' RELEASE PKR, RUN THROUGH PERFS TO KN F & TEST PKR TO 500# ND BOR NULERAC TR	F. PLACE 500# ON BACKSIDE & COT 3 1 1985 S MIN, 10 MIN, & 15 MIN SITP. COT 3 1 1985 NOCK OFF BALL SEALERS
RESET PKR @ +/- 3600' LOAD BACKSIDI		<b>(5)</b> 8.5 (25) (3.5 (3.5 (3.5 (3.5)))
RESET PKR @ +/- 3600'. LOAD BACKSIDI 9. FRAC GRAYBURG PERFS 3688'-3726' W/ OTTOWA SAND @ AN AVERAGE RATE C BACKSIDE & MONITOR THROUGHOUT JO	29,000 GALLONS 35# BORATE XLG 2% KCL CA PF 25 BPM W/ MAX PRESSURE NOT TO EXCEE	ED 5000#. PLACE 500# ON
RESET PKR @ +/- 3600'. LOAD BACKSIDI 9. FRAC GRAYBURG PERFS 3688'-3726' W/ OTTOWA SAND @ AN AVERAGE RATE C BACKSIDE & MONITOR THROUGHOUT JO 10. FLOWBACK WELL @LESS THAN 1 BPM.	29,000 GALLONS 35# BORATE XLG 2% KCL CA )F 25 BPM W/ MAX PRESSURE NOT TO EXCEE OB.	:D 5000#. PLACE 500# ON
RESET PKR @ +/- 3600'. LOAD BACKSIDI 9. FRAC GRAYBURG PERFS 3688'-3726' W/ OTTOWA SAND @ AN AVERAGE RATE C BACKSIDE & MONITOR THROUGHOUT JO	29,000 GALLONS 35# BORATE XLG 2% KCL CA )F 25 BPM W/ MAX PRESSURE NOT TO EXCEE OB.	:D 5000#. PLACE 500# ON

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or