

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-0288

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

SEP 16 1993

WELL API NO.
30-015-27091

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
E-7811

7. Lease Name or Unit Agreement Name
Cedar Breaks "2" State

8. Well No.
1

9. Pool name or Wildcat
Loco Hills San Andres/Grayburg

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3629' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Mewbourne Oil Company

3. Address of Operator
P.O. Box 5270 Hobbs, New Mexico 88241

4. Well Location
Unit Letter G : 2130 Feet From The North Line and 1980 Feet From The East Line
Section 2 Township 18S Range 30E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3629' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Plug back to different reservoir <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

09/07/93 Perforate San Andres from 3550'-56', 3570'-74', 3582'-86'. Set CIBP at 6850'.
09/08/93 TIH w/tbg. & pkr. Acidize w/2800 gals. 15 HCL acid & swab test.
09/09/93 Acidize w/20,000 gals. 20% HCL. Swab test.
09/10/93 Set retrievable bridge plug at 3528'. Perforate Grayburg from 3348'-64', 3414'-21', 3454'-60', 3478'-94', 3504'-14'. Acidize w/5000 gal. 15% HCL acid. Swab test.
09/11/93 Frac Grayburg with 40,000 gal. gelled water & 78,000# sand.
09/12/93 Pull retrievable bridge plug and TIH w/production string.
09/13/93 Install pumping unit and test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Erick W. Nelson TITLE Engineer DATE 09/15/93
(505)

TYPE OR PRINT NAME Erick W. Nelson TELEPHONE NO. 393-5905

(This space for State Use)

ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE SEP 29 1993

CONDITIONS OF APPROVAL, IF ANY:

