

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088
JAN 25 1994

WELL API NO.
30-015-27732

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
647

7. Lease Name or Unit Agreement Name

Illinois Camp "17" State #2

8. Well No.
2

9. Pool name or Wildcat
Illinois Camp Morrow, North (und.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Mewbourne Oil Company

3. Address of Operator
P. O. Box 5270; Hobbs, New Mexico 88241

4. Well Location
Unit Letter J : 1980 Feet From The South Line and 1980 Feet From The East Line

Section 17 Township 18S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3616 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
☒ CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1-06-94: Drilled 8 3/4" production to a total depth of 10,570' KB. Ran electric logs and evaluated same.

1-07-94: Ran 5 1/2" production casing to a total depth of 10,570'.
Ran 262 joints of new and used 17#, S-95, N-80, and K-55, 8rd, LTC casing and set @ 10,570' KB. Howco cemented first stage with 1350 sacks of Class "H" containing 6/10% Halad 322 + 5#/sk. Silicalite + 2 1/2#/sk. salt. Plug down to 10,535' @ 8:00 AM, 1-7-94. Opened DV tool @ 7451' and cemented 2nd stage with 1100 sacks of Class "H" Lite containing 1#/sk. flocele + 5#/sk. gilsonite + 5#/sk. salt followed by 600 sacks of Class "H" containing 6/10% Halad 322 + 5#/sk. silicalite + 2 1/2#/sk. salt. Plug down to 7451' @ 12:00 noon, 1-7-94. Circulated 250 sacks off of first stage and 220 sacks to the pit on the second stage. Set SLips and release rig @ 5:00 PM, 1-7-94.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bill Pierce TITLE Drilling Superintendent DATE 1-21-94

TYPE OR PRINT NAME Bill Pierce TELEPHONE NO. 505 393-5905

(This space for State Use)

SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE FEB 18 1994

CONDITIONS OF APPROVAL, IF ANY: