			NM OIL CONS COMMISSION
			Drawer DD
Form 3160-5	UNITED S	STATES	Artesia NM 88210
June 1990)	DEPARTMENT OF		Budget Bureau No. 1004-0135
- ··· ,	BUREAU OF LAND		Expires: March 31, 1993 5. Lease Designation and Serial No.
		MAMOLALI	
SUNDRY NOTICES AND REPORTS ON WELLS		<u>LC-067136</u> 6. If Indian, Allottee or Tribe Name	
		to deepen or reentry to a different rese RMIT—" for such proposals	rvoir.
SUBMIT IN TRIPLICATE			7. If Unit or CA, Agreement Designation
			8. Well Name and No.
2. Name of Operator		(505) 7/9 1/71)	Scout EH Federal Com #6
	CUM CORPORATION	(505) 748-1471)	9. API Well No.
3 Address and Telephone No.	St., Artesia, NM 8	8210	30-015-28499 10. Field and Pool, or Exploratory Area
	Sec., T., R., M., or Survey Description		Penasco Draw Wolfcamp
		n 34-T18S-R25E (Unit G, SWNE)	11. County or Parish, State
			Eddy Co., NM
12. CHECK A	PPROPRIATE BOX(s) TO	D INDICATE NATURE OF NOTICE, I	REPORT, OR OTHER DATA
TYPE OF S	UBMISSION	TYPE OF ACTION	
Notice of 1	Intent		Change of Plans
		Recompletion	New Construction
X Subsequen	it Report	Plugging Back	Non-Routine Fracturing
•		Casing Repair	Water Shut-Off
		= • · • · •	the share share on
Final Aba	ndonment Notice	Altering Casing	Conversion to Injection
🗌 Final Aba	ndonment Notice		<u>Conversion</u> to Injection <u>g & cmt</u> Dispose Water
		Altering Casing	<u>g & cmt</u> (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form)
13 Describe Proposed or Comp give subsurface location TD 6202'. Re (6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes	pleted Operations (Clearly state all pertin ons and measured and true vertical dept eached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh s, OK. Circulated 1 ed BLM - Carlsbad p	Altering Casing	Conversion to Injection <u>g & cmt</u> ☐ Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled. -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug, to 2300 psi at 3.50 AM (6-9-95. izers) on alternate joints
13 Describe Proposed or Comp give subsurface location TD 6202'. Re (6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi	pleted Operations (Clearly state all pertin ons and measured and true vertical dept eached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh s, OK. Circulated 1 ed BLM - Carlsbad p	Altering Casing The Altering Casing The Production casin when details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig	Conversion to Injection <u>g & cmt</u> Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled. -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug, to 2300 psi at 3.50 AM (6-9-95.
13 Describe Proposed or Comp give subsurface location TD 6202'. Re (6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi from TD to 53	pleted Operations (Clearly state all pertin ons and measured and true vertical dept eached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh s, OK. Circulated 1 ed BLM - Carlsbad p	Altering Casing Tother Production casin Nother Production casin tent details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig rior to job. Used 11 central	Conversion to Injection g & cmt Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) : of starting any proposed work. If well is directionally drilled. -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt Bumped plug, to 2300 psi at 30 AM (6-9-95
13 Describe Proposed or Comp give subsurface location TD 6202'. Re (6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi from TD to 53	pleted Operations (Clearly state all pertin ons and measured and true vertical dept eached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh s, OK. Circulated 1 ed BLM - Carlsbad p 600'.	Altering Casing The Altering Casing The Production casin when details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig	Conversion to Injection <u>g & cmt</u> Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled, -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug to 2300 psi at 3: 10 AM 6-9495 izers' on alternate joints
13 Describe Proposed or Comp give subsurface location TD 6202'. Re (6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi from TD to 53	pleted Operations (Clearly state all pertin ons and measured and true vertical dept eached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh s, OK. Circulated 1 ed BLM - Carlsbad p 600'.	Altering Casing Tother Production casin Nother Production casin tent details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig rior to job. Used 11 central	Conversion to Injection <u>g & cmt</u> Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled. -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug, to 2300 psi at 3: 10 AM 6-9495 izers on alternate joints
13 Describe Proposed or Comp give subsurface location TD 6202'. Re (6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi from TD to 53	pleted Operations (Clearly state all pertin ons and measured and true vertical dept eached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh s, OK. Circulated 1 ed BLM - Carlsbad p 600'.	Altering Casing Tother Production casin Nother Production casin tent details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig rior to job. Used 11 central	Conversion to Injection <u>g & cmt</u> Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled. -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug, to 2300 psi at 3: 10 AM 6-9495 izers on alternate joints
13 Describe Proposed or Comp give subsurface location TD 6202'. Re (6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi from TD to 53	pleted Operations (Clearly state all pertin ons and measured and true vertical dept eached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh s, OK. Circulated 1 ed BLM - Carlsbad p 600'.	Altering Casing Tother Production casin Nother Production casin tent details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig rior to job. Used 11 central	Conversion to Injection <u>g & cmt</u> Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled, -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug to 2300 psi at 3: 10 AM 6-9495 izers' on alternate joints
13 Describe Proposed or Comp give subsurface location TD 6202'. Re (6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi from TD to 53	pleted Operations (Clearly state all pertin ons and measured and true vertical dept ached TD at 6:30 PM casing set at 6202 625 sacks Pacesette weight 12.5). Taile 1 (yield 1.69, weigh s, OK. Circulated 1 ed BLM - Carlsbad p 300'.	Altering Casing Tother Production casin Nother Production casin tent details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig rior to job. Used 11 central	Conversion to Injection <u>g & cmt</u> Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled, -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug to 2300 psi at 3: 10 AM 6-9495 izers' on alternate joints
 13 Describe Proposed or Compere subsurface location TD 6202'. Re(6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi from TD to 53 Waiting on co Waiting on co 14 Thereby certify that the for Signed Wutt 	pleted Operations (Clearly state all pertin ons and measured and true vertical dept ached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh c, OK. Circulated 11 ed BLM - Carlsbad po 600'.	Altering Casing Tother Production casin Nother Production casin tent details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig rior to job. Used 11 central	Conversion to Injection <u>g & cmt</u> Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled, -1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug to 2300 psi at 3: 10 AM 6-9495 izers' on alternate joints
 13 Describe Proposed or Comperent subsurface location TD 6202'. Re(6218.39') of Cemented with (yield 1.96, 8#/sack hisea for 5 minutes NOTE: Notifi from TD to 53 Waiting on co 	pleted Operations (Clearly state all pertin ons and measured and true vertical dept ached TD at 6:30 PM casing set at 6202 a 625 sacks Pacesetto weight 12.5). Tailo al (yield 1.69, weigh c, OK. Circulated 11 ed BLM - Carlsbad po 600'.	Altering Casing Tother Production casin Nother Production casin tent details, and give pertinent dates, including estimated date this for all markers and zones pertinent to this work.)* 6-7-95. Ran 139 joints of 5 '. Float shoe set at 6202'. er Lite C, 10#/sack gilsonite ed in with 225 sacks Super C, ht 13.0). PD 11:30 PM 6-8-95 20 sacks. WOC. Released rig rior to job. Used 11 central Markets	<pre>Gent Conversion to Injection g & cmt Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) of starting any proposed work. If well is directionally drilled1/2" 15.5# J-55 LT&C Float collar set at 6154'. and 1/4#/sack celloseal .4% CF-2, 5#/sack salt and . Bumped plug, to 2300 psi at 3:30 VAM 6-9495. izers on alternate joints Oile Conversion of the set of the</pre>

=: