## Submit 3 Copies to Appropriate District Office

## State of New Mexico Ene. Minerals and Natural Resources Department

Form C-103 Revised 1-1-89	1
Revised 1-1-89	U

DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088

DISTRICT II

Santa Fe, New Mexico 87504-2088

	30-015-28877		
5.	Indicate Type of Lease	EEE	
	CTATE!	EEE	K X

WELL API NO.

SUNDRY NOTICES AND REPORTS ON WELLS  DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:  OLAS WELL X OTHER  WELL X OTHER  Ryburn FZ  8. Well No.  3  Address of Operator 105 South 4th St., Artesia, NM 88210  Well Location Unit Letter M : 990 Feet From The South Line and 990 Feet From The West Line Section 22 Township 18S Range 26E NMPM Eddy County  10. Elevation (Show whether DF, RKB, RT, GR, etc.)  3340' GR  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  RFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT LILOR ALTER CASING  CASING TEST AND CEMENT JOB	P.O. Drawer DD, Artesia, NM 88210		STATE FEE KX	
DO NOT USE THIS FORM FOR PROPOSALS TO DRILLO RTO DEEPER OR PLUG BACK TO A  DIFFERENT RESERVOIR. US: "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:  "Well.	DISTRICT III 000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease No.	
DO NOT USE THIS FORM FOR PROPOSALS TO DRILLO RTO DEEPER OR PLUG BACK TO A  DIFFERENT RESERVOIR. US: "APPLICATION FOR PERMIT"  (FORM C-101) FOR SUCH PROPOSALS.)  Type of Well:  "Well.	SUNDRY NOTICES AND REPORTS ON WELLS			
ONL WALL OTHER PROPERTY OF THE	DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN DIFFERENT RESERVOIR. USE "APPLICATION FOR PE	OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name	
Name of Operator	Type of Well: Oil V GAS		Ryburn F7	
Addres O'Perrator 105 South 4th St., Artesia, NM 88210  Well Lossion Unit Letter M: 990 Feet Front The South Line and 990 Peet Front The West Line Section 22 Township 18S Range 26E NMPM Eddy County 10. Elevation (Show whether DF, RKB, RT, GR. stc.) 3340' GR  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO:  REFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT LLOR ALTER CASING CASING TEST AND CEMENT JOB OTHER: Production casing & cement X  Leochibe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  Casing test and CEMENT JOB OTHER: Production casing & cement X  Commence Drilling OPNS. Plug And Abandonment LLOR ALTER CASING Test And CEMENT JOB OTHER: Production casing so cament X  Commenced Plug And Abandon Advanced Action of See Perinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  Casing test and CEMENT JOB OTHER: Production casing & cement X  Commenced Plug And Abandon Action of See Plug And Action of See Plug And Action of See Plug Action Casing any proposed work) SEE RULE 1103.  Casing test and CEMENT JOB OTHER: Production casing & cement X  Commenced Plug And Action of See Plug A				
Well Location  Until Letter M : 990 Feet From The South  Line and 990 Feet From The West Line  Section 22 Township 18S Range 26E NMPM Eddy County  10. Elevation (Show whether DF, RKB, RT, GR. etc.)  3340' GR  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT LICOR ALTER CASING CHANGE PLANS OTHER: Production casing & cement X  Describe Proposed or Completed Operations (Clearly state all perimens details, and give periment dates, including estimated date of starting any proposed word) SEE RULE 1103.  TD 1897' Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yteld 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 9 1996  ONL CONS. DIV.  hereby centry blacks information above, if true and complete to the best of my trowledge and belief.  Production Clerk			_	
Well Lotter M : 990 Feet From The South Line and 990 Feet From The West Line  Section 22 Township 188 Range 26E NMPM Eddy County  10 Elevation (Show whether DF, RKB, RT, GR, etc.)  3340 GR  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REPORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Production casing & cement X  Describe Proposed or Completed Operations (Clearly state all perinent datas), and give perinent dates, including estimated date of starting any proposed worth SEE RULE 1103.  TD 1897'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, 0K. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 29 1996  Oll. CONS. DIV.  hereby cently which information above if true and complete to the best of my knowledge and belief.  Production Clerk  Production Clerk  Production Clerk			9. Pool name or Wildcat	
Unit Letter M : 990 Feet From The South Line and 990 Feet From The West Line  Section 22 Township 18S Range 26E NMFM Eddy County  10 Elevation (Show whether DF, RKB, RT, GR, etc.)  3340' GR  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB  HER: OTHER: Production casing & cement X  Describe Proposed or Completed Operations (Clearly state all perimenal details, and give perimenal dates, including estimated date of starting any proposed worth) SEE RULE 1103.  TD 1897' Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 0 1926  OTHER: Production Clerk  APR 2 0 1926  OTHER: Production Clerk  Production Clerk  APR 2 0 1926			Atoka San Andres	
Section 22 Township 18S Range 26E NMPM Eddy County 10. Elevation (Show whather DF, RKB, RT, GR. etc.) 3340' GR  Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:  REGORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Production casing & cement  LL OR ALTER CASING OTHER: Production casing & cement  Work) SEE RULE 1103. TD 1897'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 29 1996  OTHER Production Clerk PATE 4-25-96		Line and990	Feet From The West Line	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  REFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Production casing & cement Tobact Work) SEE RULE 1103.  TO 1897'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1833'. Cemented with 600 sacks Class C Neat (yleld 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 9 1996  Office Comments of the best of my knowledge and belief.  Production Clerk DATE 4-25-96	100			
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  NOTICE OF INTENTION TO:  REFORM REMEDIAL WORK			WITH 11/1/////////////////////////////////	
NOTICE OF INTENTION TO:  REFORM REMEDIAL WORK  PLUG AND ABANDON  ALTERING CASING  ALTERING CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER: Production casing & cement  To casing set at 1895'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped with 600 psi for 1 minute, 0K. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 9 1996  OIL CON. DIV.	'///////		<i>VIIIIIIIIIIIII</i>	
NOTICE OF INTENTION TO:  REFORM REMEDIAL WORK  PLUG AND ABANDON  ALTERING CASING  ALTERING CASING  COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT  CASING TEST AND CEMENT JOB  OTHER: Production casing & cement  To casing set at 1895'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped with 600 psi for 1 minute, 0K. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 9 1996  OIL CON. DIV.	Check Appropriate Box to Indicate	Nature of Notice, Re	port, or Other Data	
MPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING CASING TEST AND CEMENT JOB OTHER: Production casing & cement X  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  TD 1897'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 9 1996  OTHER: Production Clerk PLUG AND ABANDONMENT ABANDO	* • *	SUBS	SEQUENT REPORT OF:	
COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB OTHER: Production casing & cement North SEE RULE 1103.  TD 1897'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 9 1996  OIL CON. DIV.  Diff. 2  Production Clerk  Page 4-25-96	REFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING		
CASING TEST AND CEMENT JOB  HER: OTHER: Production casing & cement X  2. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  TD 1897'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 9 1996  OIL GON. DIV.	(——)	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT		
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  TD 1897'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2 9 1996  OIL, GON., DIV., DIV.		CASING TEST AND CEMENT JOB		
TD 1897'. Reached TD at 4:30 AM 4-17-96., Ran 45 joints of 5-1/2" 15.5# J-55 (2002.46') of casing set at 1895'. Float shoe set at 1895'. Float collar set at 1853'. Cemented with 600 sacks Class C Neat (yield 1.32, weight 14.8). PD 11:20 AM 4-17-96. Bumped plug to 1800 psi for 1 minute, OK. Circulated 113 sacks. WOC. Released rig at 3:30 PM 4-17-96.  Waiting on completion unit.  APR 2.9 1996  OIL. GON. DIV.  Diff. 2  Production Clerk  Production Clerk  Page 4-25-96	THER:	OTHER: Production casing & cement X		
Waiting on completion unit.  APR 29 1996  OIL GON. DIV.  I hereby certify that the information above if true and complete to the best of my knowledge and belief.  Production Clerk  Production Clerk  Production Clerk  Page 4-25-96	work) SEE RULE 1103.  TD 1897'. Reached TD at 4:30 AM 4-17-96., of casing set at 1895'. Float shoe set at with 600 sacks Class C Neat (yield 1.32, we plug to 1800 psi for 1 minute, OK. Circula	Ran 45 joints of 1895'. Float co ight 14.8). PD	5-1/2" 15.5# J-55 (2002.46') llar set at 1853'. Cemented ll:20 AM 4-17-96. Bumped	
OIL CON. DIV.  I hereby certify that the information above if true and complete to the best of my knowledge and belief.  Production Clerk  Production Clerk  Production Clerk  Production Clerk			RICHUED	
I hereby certify that the information above if true and complete to the best of my knowledge and belief.  Production Clerk  PATE 4-25-96	Waiting on completion unit.		APR 2.9 1996	
Production Clerk PATE 4-25-96				
	I hereby certify that the information above if true and complete to the best of my knowledge an			
	SIGNATION Kusta Tille	Production C	lerk <u>DATE</u> 4-25-96	
	Rusty Klein		TELEPHONE NO. 505/748-	

(This space for State BRIGINAL SIGNED BY TIM W. GUM

DISTRICT II SUPERVISOR

APR 3 0 1996

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY-