

37. SUMMARY OF POROUS ZONES. (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION		TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	GEOLOGIC MARKERS		
					NAME	MEAS. DEPTH	TRUE VERT. DEPTH
		0'	400'	Caliche & Redbed	T. Seven Rivers	2110'	
		400'	550'	Anhydrite	T. Queen	2732'	
		550'	1500'	Salt	T. Grayburg	3205'	
		1500'	3830'	Dolomite, Sand & Anhydrite	T. San Andres	3623'	

RECEIVED
APR 29 1997
BLM
ROSWELL, NM