

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries).

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	38. GEOLOGIC MARKERS		
				NAME	MEAS. DEPTH	TOP TRUE VERT. DEPTH
	0'	500'	Caliche & Redbed	T. Seven Rivers	2160'	
	500'	650'	Anhydrite	T. Queen	2835'	
	650'	1700'	Salt	T. Grayburg	3240'	
	1700'	3950'	Dolomite, Sand & Anhydrite	T. San Andres	3670'	