

37. SUMMARY OF POROUS ZONES. (Show all important zones of porosity and contents thereof, cored intervals, and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries).

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP	
					MEAS. DEPTH	TRUE VERT. DEPTH
	0'	390'	Caliche & Redbed	T. Seven Rivers	2093'	
	390'	550'	Anhydrite	T. Queen	2782'	
	550'	1600'	Salt	T. Grayburg	3213'	
	1600'	3950'	Dolomite, Sand & Anhydrite	T. San Andres	3680'	

38. GEOLOGIC MARKERS