

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS			
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	TOP		
					MEAS. DEPTH	TRUE VERT. DEPTH	
Rustler	297	520					
Salado	520	1471					
Tansill	1471	1633					
Yates	1633	2000					
Seven Rivers	2000	2669					
Artesia (Queen)	2669	3076					
Grayburg	3076	3520					
San Andres	3520	3795 (TD)					
DEPTH							ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.. (continued from the front)