		NN	I. OII CONS. UIVISION		/
		041	C 1et 51 6		ASF
		Arte	sia, NM RECEIVE		$C[\mathcal{I}]$
Form 3160-5 (June 1990)			RECEIVE	ED FORM APPROVED	
(June 1990)		OF THE INTERIOR	1997 AUG -6 A	Budget Bureau No. 1004-0135	
		ND MANAGEMENT		5. Lease Designation and Serial No.	
<b>D</b>	SUNDRY NOTICES A	ND REPORTS ON WE	LLS PUREAU OF LAN	NM-96220	
Do not use this	form for proposals to drill Use "APPLICATION FOR I	OF 10 deepen or reentry	to a different recording -1	) & Mindian, Allottee or Tribe Name ICE	
SUBMIT IN TRIPLICATE				7. If Unit or CA, Agreement Designati	ION
1. Type of Well			AUG 1 5 1997	, 12	
Oil Well X Gas 2. Name of Operator	I Other			8. Well Name and No.	
YATES PETROLEUM CORPORATION (505) 48-1471 N. ON				Arenas ARI Fed Com #	∦1
3. Address and Telephone No.				9. API Well No.	
105 South 4th St., Artesia, NM 88210 DIST. 2				30-015-29629 10. Field and Pool, or Exploratory Area	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Turkey Track Morrow,	
1650' FSL &	1650' FWL of Sectio	n 15-T18S-R29E (Un	nit K, NESW)	11. County or Parish, State	NOFCO
12. CHECK				Eddy Co., NM	
STEER AT HOMMATE BOA(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION TYPE OF ACTION				·····	
Notice	of Intent	Abandonment		Change of Plans	
Subseq	uent Report	kecompletion		New Construction	
	AUS 1	3 1997 Plugging Back		Non-Routine Fracturing	
Final A	AUU 1	Altering Casi		Water Shut-Off	
		Other	·	Dispose Water	
11		······································		(Note: Report results of multiple completion on Completion or Recompletion Report and Log for	
13. Describe Proposed or Co give subsurface loc	ompleted Operations (Clearly state all per cations and incasured and true vertical d	tinent details, and give pertinent date epths for all markers and zones pert	s, including estimated date of starting an	ny proposed work. If well is directionally of	drilled,
7-22-97 - C	leaned location, set	and tested anchor	rs. Moved in and r	igged up pulling unit	<del>r</del>
7-22-97 - Cleaned location, set and tested anchors. Moved in and rigged up pulling unit. 7-23-97 - Installed BOP and tested casing to 2300 psi. TIH with bit, scraper and 2-7/8"					
tubing to 11551'. Reversed 25 bbls 2% KCL water to pit. TOOH. Rigged up wireline TTH					
with logging tools.and ran CBL/CCL/GR log. TOOH with logging tools.and rigged down wireline.					
7-24-97 - Rigged up wireline. TIH with 4" casing guns and perforated 11149-11177' w/54					
.46" holes as follows: 11149-11152' and 11173-11177' (6 SPF Morrow). TOOH with casing					
guns and rigged down wireline. TIH with packer and tubing to 11186'. Pickled tubing with					
250 gallons 15% NEFE acid. Spot 2 bbls 7-1/2% iron control HCL acid. Pulled up and set					
packer at 11092'. Removed BOP. Nippled up wellhead. Pressured annulus. Got communication on tubing side. Tried to reset packer and test - would not hold. Nippled down wellhead					
and installed BOP. TOOH with packer. TIH with new packer and tubing. Set packer at					
11092'. Removed BOP and nippled up wellhead. Tested annulus to 1800 psi. Swabbed					
tubing dry.					
7-25-97 - Installed treesaver. Pressured annulus to 1500 psi. Acidized perforations 11149-11177' with 10000 scf/N2 pad, 2000 gallons 7-1/2% iron control HCL acid with 1000					
scf/bbl N2 and ball sealers. Opened well and flowed well back. Shut well in.					
7-26-97 nop	pened well and flare	d down to pit. Lo	paded tubing with 2%	% KCL water. Nippled	ł
14. I hereby ceptify that the	e foregoing is tree and correct		CONTIN	UED ON NEXT PAGE:	
Signed Kus	tin fler			Date Aug. 4, 1997	
(This space for Foderal	de State office use)				
Approved by		Title		Date	
Conditions of approval,	, if any:				
		•			
		wingly and willfully to make to any	department or agency of the United Sta	ates any false, fictitious or fraudulent state	ements
or representations at to any	matter within its jurisdiction.			terret de la transmer de la seconda	

\*See Instruction on Reverse Side

YATES PETROLEUM CORPORATION Arenas ARI Federal Com #1 Section 15-T18S-R29E Eddy County, New Mexico

## SUNDRY NOTICE CONTINUED:

down wellhead and installed BOP. Unset packer. TOOH. Rigged up wireline. TIH with 3-1/2" casing guns and perforated 11074-11103' w/56 .45" holes as follows: 11074-11078', 11083-11084' and 11097-11103' (4 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with RBP, packer and 2-7/8" tubing. Set RBP at 11137' and tested to 1700#. Spot 2 bbls 7-1/2% iron control HCL acid across perforations. Pulled up and set packer at 11011'. Removed BOP and nippled up wellhead. Tested annulus to 1600 psi. Swabbed tubing dry. Acidized perforations 11074-11103' with 1500 gallons 7-1/2% iron control HCL acid with 1000 scf/bbl N2. Opened well to recover acid load. 7-27-28-97 - Continue flowing well. Shut well in. 7-29-97 - Opened well and flared down to pit. Loaded tubing with 2% KCL water. Removed BOP and nippled up wellhead. Unset packer. TOOH. TIH with 4" casing guns and perforated 11017-11043' w/68 .45" holes as follows: 11017-11022', 11027-11032' and 11039-11043' (4 SPF - Morrow). TOOH with casing guns and rigged down wireline. TIH with packer and 2-7/8" tubing. Unset RBP at 11137'. Pulled up and set RBP at 11062'. Could not get RBP to test. Pulled up to 10870' and reset tools. Could not get RBP or packer to test. Unset packer and RBP. TOOH - did not have RBP. TIH to retrieve RBP. 7-30-97 - TOOH with tubing and RBP. RBP was dragging. Got RBP hung up at 10140'. Pushed RBP back down to 11520' and got off RBP. TOOH with tubing. TIH with RBP, packer and tubing. Set RBP at 11062' and tested to 2600 psi. Pulled up and set packer at 10927'. Removed BOP and nippled up wellhead. Tested annulus to 1600 psi. tubing dry. Installed treesaver. Acidized perforations 11017-11043' with 10000 scf N2 pad, 2000 gallons 7-1/2% iron control HCL acid with 1000 scf/bbl N2. Removed treesaver. Opened well to pit to recover acid load. 7-31-97 - Flowed well. Shut well in.

Rusty Klein Operations Technician August 4, 1997