30-015-29788

OARID 6137 PROD 25883 POOI 3610 PB

Z-10-98

Microlog
1109'-1802'

Natural Damma Ray
1109'-1802'

Comp: Neutron
200'-1802'

Compinuthal Rateralog
1109'-1802'

Coment Bond day

Surf-1785'

Submit 3 Copies to Appropriate District Office			of New Mexico Natural Resources Departn	Form C-103 C S F Revised 1-1-89
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 DISTRICT II P.O. Drawer DD, Artesia, NM 88210		P.C	EVATION DIVISION D. Box 2088 v Mexico 87504-2088	WELL API NO. 30-015-29788 5. Indicate Type of Lease STATE FEE
DISTRICT III 1000 rio Brazos Rd, Aztec, NM 87410			V Mexico 87304-7033 - 12.37256	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN ON PLUG BACK TO A Lease Name or Unit Agreement Name Aloka San Andres Unit (FORM C-101) FOR SUCH PROPOSALS.)				
Oil Ges Well Well	Olher		(E) 10/A	
2. Name of Operator V DEVON ENERGY	PRODUCTION COMPANY, L.P.		C5750561 81 TI 31 CI XI	8. Well No.
3. Address of Operator				9. Pool name or Wildcat
20 NORTH BROADWAY, SUITE 1500, OKLAHOMA CITY, OKLAHOMA 73102 (405) 235-3611				Atoka San Andres
4 Well Location Unit Letter D:175 Feet From The North Line and 375 Feet From The West Line				
Section 14	Township 18S	Range		Eddy County
	//////////////////////////////////////	how whe	ther DF, RKB, RT, GR, etc.)	
Check Appropriate Box To Indicate Nature Of Notice, Report, Or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT CASING TEST AND CEMENT JOB COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT COMMENCE DRILLING OPNS. PLUG AND ABANDON C				
SIGNATURE TYPE OR PRINT NAME	ion above is true and complete to the best of the formal f		ENGINEERING TECHNICIAN	DATE <u>6/28/00</u> TELEPHONE NO. (405) 235-3611
(This space for State use) Approved by Conditions of approval, if any:	in W. Sum	TITLE	Ristrict Separvisor	DATE UL 0 6 2000