

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals, and all drill-stem tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	MEAS. DEPTH	TOP TRUE VERT. DEPTH
	0'	455'	Caliche & Redbed	T. Seven Rivers	2055'	
	455'	610'	Anhydrite	T. Queen	2740'	
	610'	1590'	Salt	T. Grayburg	3120'	
	1590'	3988'	Dolomite, Sand & Anhydrite	T. San Andres	3560'	