

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-015-31148

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
V-5667

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. Name of Operator
YATES PETROLEUM CORPORATION

3. Address of Operator
105 South 4th St., Artesia, NM 88210

4. Well Location
Unit Letter A : 660 Feet From The North Line and 660 Feet From The East Line
Section 16 Township 18S Range 25E NMPM Eddy County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3537' GR

7. Lease Name or Unit Agreement Name
Tumbledink AVK State Com

8. Well No.
1

9. Pool name or Wildcat
Richard Knob Atoka-Morrow

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Change out tubing from 3-1/2" to 2-7/8" ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2-28-2001 - Moved in and rigged up pulling unit.

3-1-2001 - TIH and set blanking plug in packer at 8353'. Blow down tubing. Nippled down tree and nipped up BOP. Started out of hole with 3-1/2" tubing, laying down. Shut well in.

3-2-2001 - Finished TOOH with 3-1/2" tubing. TIH with 2-7/8" tubing with on/off tool and engaged packer at 8353'. Nippled down BOP and nipped up tree. Swabbed tubing down to 7000'. Shut well in.

3-3-2001 - Swabbed down tubing. Pulled blanking plug. Rigged up coiled tubing unit and N2. TIH with coiled tubing and tagged fill at 8515'. Drilled thru to 8568' with stringers to 8600'. Worked bit thru area several times until clean. TIH to 8780'. Circulate hole clean. Blowed hole dry with coiled tubing. TOOH with coiled tubing. Rigged down coiled tubing unit and N2. Shut well in. Released well to production department.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Rusty Klein TITLE Operations Technician DATE Nov. 8, 2001
TYPE OR PRINT NAME Rusty Klein TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR

NOV 13 2001

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: