Submit 3 Copies To Appropriate D	District C.			c1	$\Lambda\Lambda$
Office District I	Sia	te of New N			Form C-103
1625 N. French Dr., Hobbs. NM 8	7240	ierais and Na	tural Resources	WELL	Revised March 25, 1999
District II		TEDU ATIO	N. Dir waray	WELL API NO	
811 South First, Artesia, NM 8721 District III			N DIVISION	5. Indicate Typ	0-015- 3(190
1000 Rio Brazos Rd., Aztec, NM 8	5/410	40 South Pa		STATE	
District IV 2040 South Pacheco, Santa Fe, NM	Sar.	ita Fe, NM	87505		Gas Lease No.
				9. State 911 &	
(DO NOT USE THIS FORM FOR	NOTICES AND REPORT	TS ON WELL	.S	7. Lease Name	or Unit Agreement Name:
	"APPLICATION FOR PERMIT"	O DEEPEN OR P ' (FORM C-101)	LUG BACK TO A		
PROPOSALS.) 1. Type of Well:		(1010)	OKSOCII	DAR COUNTY	ony State
Oil Well Gas V	Vell 🔀 Other			011 Com 4	sud state
2. Name of Operator V	Vell 🔀 Other	-			
- -	XY USA Inc.		16696	8. Well No.	
3. Address of Operator			10090	O Pool	*****
	O. BOX 50250 MIDLA	ND, TX 7971	10-0250	9. Pool name or	Wildcat
4. Well Location		· · · · · · · · · · · · · · · · · · ·		wiesz. Twhile	Morrow, South
Unit Letter 🔥	.115 5.5				
Om Letter 14	feet from	the Nort	line and	feet fr	om the East line
Section 16	Townsh	ip 185 R	lange Z9E	- -	
	10. Elevation (Si	how whether I	DR, RKB, RT, GR, etc.	NMPM E	DDY County
		3460			
11. Ch	eck Appropriate Box t	o Indicate N	lature of Notice.	Report or Other	Data
NOTICE	JE INTENTION TO:		SUB	SEQUENT RE	
PERFORM REMEDIAL WOR	RK 🔲 PLUG AND ABAN	DON 🔲	REMEDIAL WOR	K	ALTERING CASING
TEMPORARILY ABANDON	CI CHANGE DI MIG				ALTERING CASING
	☐ CHANGE PLANS		COMMENCE DRI	LLING OPNS.	PLUG AND
PULL OR ALTER CASING	☐ MULTIPLE		CASING TEST AN	אר בי	ABANDONMENT
	COMPLETION		CEMENT JOB	ND 🔀	
OTHER:			OTHER:		
12. Describe proposed or co	ompleted operations (Clea	rly state all ne	mtim and distribution		
O , 1	work). SEE RULE 1103.	For Multiple	Completions: Attack	wellbore discre-	including estimated date
or recompilation.		1	ompletions. Attacl	i welloofe diagram	of proposed completion
		- del			
	(510			
		"\ /			•
					.
	;	(/			•
	,			A.	
	See of	ther 5	ide		LIVED
					W/0810
					'1
I hereby certify that the inform	nation above is true and co	mplete to the	best of my knowledg	ge and belief.	
SIGNATURE V	fff				,
	700	TITLE	REGULATORY A	NALYST	DATE 72500
Type or print name	DAVID STEWART			Telephone No. 014	• —
(This space for State use)				Telephone No. 915	-083-3/1/
	Am W. Su	· sw	District Sy	pervisor	44a
APPPROVED BY	BQ	TITLE		•	_DATE AUG ₹7 2000
Conditions of approval, if any	•	· 			_~111

ATTACHMENT C-103
OXY USA INC.
OXY COW PONY STATE #1
SEC 16 T18S R29E
EDDY COUNTY, NM

NOTIFIED NMOCD 7/1/00 OF SPUD. MIRU UTI 303, SPUD WELL @ 2045hrs MDT 7/1/00. DRILL 17-1/2" HOLE TO 90' & LOST RETURNS, PUMP PILL & REGAINED RETURNS. DRILL TO 120', LOST RETURNS AGAIN, M&P LCM SWEEPS W/O SUCCESS, DRY DRILL TO TD @ 433', 7/2/00, PUMP SWEEP. RIH W/ 13-3/8" 48# H40 CSG, TAG UP @ 380', WASH DOWN TO 409', COULDN'T GET DEEPER. M&P 200sx CL H W/ 10%HNB + 10# GILSONITE + .25#/sx CELLOFLAKES + 2% CaCl₂ FOLLOWED BY 160sx 65:35 C/POZ W/ 6% BENTONITE + 2% CaCl₂ FOLLOWED BY 200sx CL C W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN 7/2/00, NO CIRCULATION DURING JOB, WOC-4hrs. NMOCD NOTIFIED BUT DID NOT WITNESS. RIH W/ 1", TAG CMT @ 135', M&P 50sx CL C W/ 4% CaCl2, POOH, WOC-3hr. RIH & TAG @ 135', DUMP 100gal PEA GRAVEL, M&P 50sx CL C W/ 4% CaCl2, POOH, WOC-1hr. RIH & TAG @ 120', DUMP 200gal PEA GRAVEL, M&P 50sx CL C W/ 4% CaCl2, POOH, WOC-1hr. RIH & TAG @ 94', DUMP 300gal PEA GRAVEL, M&P 50sx CL C W/ 4% CaCl2, POOH, WOC-1hr. RIH & TAG @ 62', M&P 120sx CL C W/ 4% CaCl2, CIRCULATE 35sx CMT TO PIT, POOH, WOC-4hr. NMOCD NOTIFIED, BUT DID NOT WITNESS. CUT OFF CASING, WELD ON STARTING HEAD, TEST TO 500#, OK. NU BOP & TEST BLIND RAMS & CASING TO 500#, OK. TEST PIPE RAMS & HYDRIL TO 500#, OK. TOTAL WOC-18hrs. RIH & TAG, DRILL OUT & DRILL AHEAD 7/3/00.

DRILL 11" HOLE TO TD @ 3007', 7/7/00, CHC. RIH W/ 8-5/8" 32# CSG & SET @ 3007'. M&P 984sx 35:65 POZ/C W/ 6% BENTONITE + 2% CaCl₂ + .25#/sx CELLO-SEAL + 5#/sx GILSONITE FOLLOWED BY 200sx Cl C CMT W/ 2% CaCl₂, DISP W/ FW, PLUG DOWN 7/8/00, CIRCULATED 297sx TO PIT, WOC-8hrs. CUT OFF CSG & INSTALL B SEC, TEST TO 2000#, OK. NU BOP & CHOKE MANIFOLD, TEST BLIND RAMS, PIPE RAMS, CHOKE LINES, CHOKE MANIFOLD AND SAFETY VALVES TO 5000#, OK. TEST HYDRIL, MUD LINES AND CSG TO 2500#, OK. TOTAL WOC-18hrs. RIH, DO CMT & SHOE, DRILL NEW FORMATION, TEST CSG, OK. NMOCD NOTIFIED OF CSG/CMT JOB BUT DID NOT WITNESS.

was many first from six