

Power Deep 31 Fed Com #1

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof, cored intervals; and all drill stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):				38. GEOLOGIC MARKERS		
FORMATION	TOP	BOTTOM	DESCRIPTION, CONTENTS, ETC.	NAME	MEASURED DEPTH	TRUE V.D.
			No Cores & No DST's	Rustler	470	
				Yates	1,820	
				Seven Rivers	2,140	
				Queen	2,765	
				Grayburg	3,105	
				San Andres	3,595	
				Bone Spring	5,150	
				Wolfcamp	8,670	
				Penn Shale	9,815	
				Strawn LS	10,680	
				Atoka Sh	10,940	
				Morrow Clastics	11,435	
				U. Miss	11,730	