OXY WOOF STATE #1

11/19/2002 CMIC: Davis

MIRU KEY plugging crew #93 NDWH NU BOP. SION

11/20/2002 CMIC: Davis

RIH tagged CIBP @ 6230' CH w/ salt gel. Spotted 25 sxs class C cmt. POOH to 5000'

11/21/2002 CMIC: Davis

Spotted 25 sxs class C cmt. POOH to 3820', spotted 25sx class C cmt. POOH w/ tbg NDWH RIH could not get csg speared.

11/22/2002 CMIC: Davis

Speared csg free point csg. RU wireline RIH cut csg @ 3200'. RD wireline. Started POOH w/ csg. SION

11/23/2002 CMIC: Davis

RIH w/ tbg to 3250' spotted 50 sxs class c cmt. POOH w/ tbg. WOC. RIH did not tag cmt. Spotted 50 sxs class C cmt. SION

11/24/2002 CMIC: Davis

RIH tagged cmt @ 2990'. POOH to 2650' spotted 40 sxs class C cmt. POOH to 1498' CH w salt gel. Spotted 40 sxs class C cmt. POOH w/ tbg. WOC. RIH tagged cmt @ 1390'. POOH to 498' spotted 40 sxs class C cmt. WOC SION

11/25/2002 CMIC: Davis

RIH tagged cmt @ 340'. POOH w/ tbg spotted 20sxs class C surface plug. RDMO