Exhibit "F" KCS Medallion Resources, Inc.

Typical BOP Equipment Arrangement

All BOP Equipment to be 3000 psig Working Pressure or Greater



Shugart West "24" Federal "B" No. 5