					19/6	^	
Submit 3 Copies To Appropriate District	State of N	ew Mex	cico		- W	Form C-103	
Office District I	Energy, Minerals ar	nd Natur	al Resources	WELL API	V	Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II				30-015-32			
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type of Lease			
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505			STATE FEE X			
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Saina Pe, 14141 67303			6. State Oil & Gas Lease No.			
87505 SUNDRY NOTICES AND REPORTS ON WELLS				7 Lange No	me or	Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name or Unit Agreement Name:			
DIFFERENT RESERVOIR. USE "APPLICA" PROPOSALS.)	"APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Bones BAD Com		
1. Type of Well:	_ (50	34	<i>J</i>				
Oil Well Gas Well X	Other	<u> </u>	<u>(4.5)</u>	8. Well No			
2. Name of Operator  Vertex Retraction				8. Well No.			
3. Address of Operator				9. Pool name or Wildcat			
3. Address of Operator 105 S. 4th Street Artesia, NM 88210				Undesignated Boyd Morrow			
4. Well Location	· · · · · · · · · · · · · · · · · · ·			.1			
Unit Letter <u>C: 660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line							
Section 31	Township 18S	Range	26E	NMPM	Edd	y County	
Section 01	10. Elevation (Show wh						
3447' GR							
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO:  SUBSEQUENT REPORT OF:  ALTERING							
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WO			₹K 		CASING	
TEMPORARILY ABANDON				RILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB				
OTHER:			OTHER: Perfora	ate and stimula	te	X	
Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of							
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or							
recompilation.							
1/6/03 – Perforate Morrow 9004'-9010' (6 JSPF) with 4242" holes. Acidized with 750g 7-1/2% IC HCL.							
1/8/03 – Set CIBP at 8970' with 35' cement. Perforate Atoka 8844'-8852' and 8892'-8898' (4 JSPF) with 6442"							
holes. Packer set at 8672'.							
1/9/03 – Acidize with 1500g 7-1/2% IC HCL + balls. 1/13/03 – Frac with 35# CMHPG gelled 7% KCL + CO2 + 40,000# 20/40 tempered DC sand.							
1, 10, 00	, J			•			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE Jina Hurta, TITLE Regulatory Compliance Supervisor DATE January 23, 2003							
Type or print name / huert	a			Teleph	one No	. 505-748-1471	
(This space for State us)			01128				
	riginal signed by ' Natrict ii supervisi		SUM .			DATE	
APPPROVED BY Conditions of approval, if any:	TOTAL TOTAL	PRILE_				2663	