

COMPANY <i>Lindenmuth & Associates</i>		PROPERTY NAME <i>Gorman State</i>	WELL NO. <i>1</i>
DATE	LOCATION (ULSTR) <i>Ut. E - 36 - 19 - 24</i>	FOOTAGE <i>660 FNL + 1980 FWL</i>	
API NO. <i>30-015-00054</i>		POOL <i>Canyon Wolfcamp</i>	
1. Spot a 50 SX plug @ 5741' woc + tag plug 2. Spot a 25 SX plug @ 4970 3. Spot a 25 SX plug @ 3400' to cover 325. 4. Perform 5 1/2" csg @ 1050' & circulate cement up backside to surface. Shut in valve @ surface & to 1 1/2" csg to surface. 5. Set P4A marker, clean & true location. Cut off casing.		Before 	
ILLEGIBLE		12 1/2" c 80' 8 5/8" c 1000' 1050' 3350 BS TOC 4944 Perts 5741 WC 4 1/2" - 5814 PBTD 5850 7L 6100'	
CASING RECORD: 12 1/2" c 30' w/ 40 SX 5" c 1000 w/ 500 SX 2 1/2" c 5814 w/ 150 SX. Est TOC 4944 Perforations @ 5741			