

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TWO PARTS
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-24494

5. LEASE DESIGNATION AND SERIAL NO.

069991

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐

2. NAME OF OPERATOR

Mobil Oil Corporation

3. ADDRESS OF OPERATOR

Box 633, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

660' FEL & 1980' FSL Sec. 17, T-20-S, R-25-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, WT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT ON:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT

(Note: Report results of multiple completion or Well Completion or Recompletion Report and Log Book.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Plug and Abandon subject well as per attached Plugging Procedures

RECEIVED
SEP 14 1973
U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Authorized Agent

DATE 9-13-73

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

WELL WORK RECOMMENDATIONS
Proposals for Well Reconditioning and Subsurface Maintenance
Workovers, Expense DD's, PB's, and Conversions

Lease: BROWN HUMPHREY FEDERAL Well No. 1
Field: CEMETERY MORROW FIELD
County: EDDY State: NEW MEXICO

RECOMMENDED PROCEDURE:

1. PUMP DOWN 2 3/4" TUBING BRINE WATER TO KILL THE WELL
2. M.T.P.U. PULL TUBING & GUID LC-8 HW PWR OUT OF THE HOLE
3. RUN TBG & SET 100' CEMENT PLUG OVER MORROW PERFS. (9346-9434')
4. CIRCULATE HOLE TO 1700 LADEN FLUID - MUD SHOULD CONSIST OF 25 # OF GEL PER BARREL OF WATER
5. CUT OFF 5 1/2" CASING & PULL - TOP OF CEMENT IS AT 7900' - SET 100' CEMENT PLUG IN & OUT OF CUT OFF POINT
6. SET 100' CEMENT PLUG FROM 6480' to 6580'
7. SET 100' CEMENT PLUG FROM 4700' to 4800'
8. SET 100' CEMENT PLUG FROM 3000' to 3100'
9. SET 100' CEMENT PLUG FROM 2250' to 2350'
10. SET 100' CEMENT PLUG IN & OUT OF 13 3/4" CASING FROM 950' to 1050'
11. SPOT 20' OF CEMENT AT SURFACE - CUT OFF WELL HEAD & INSTALL MARKER

NOTE: PROCEDURE REVIEWED w/ LEON BECKMAN
USGS - ARTISIP 5/25/73

5/25/73

