

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TR  
(Other instruct  
verse side)CATE  
on reForm approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

NM-026114

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> <b>Converted Water Well</b>		7. UNIT AGREEMENT NAME <b>Pecos River Deep Unit</b>	
2. NAME OF OPERATOR <b>Yates Drilling Company</b>		8. FARM OR LEASE NAME <b>TR #52</b>	
3. ADDRESS OF OPERATOR <b>207 So. 4th St - Yates Bldg. - Artesia, New Mexico</b>		9. WELL NO. <b>- water well</b>	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  <b>990' FNL &amp; 2310' FWL. Sec. 28-19-27</b>		10. FIELD AND POOL, OR WILDCAT <b>-</b>	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA <b>N/4NW/4-28-19-27</b>	
14. PERMIT NO. <b>NM Water RA-5367</b>	15. ELEVATIONS (Show whether DF, RT, GR, etc.)	12. COUNTY OR PARISH <b>Eddy</b>	13. STATE <b>N. Mex.</b>

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

Cleaned out TD 1035'

After using this water well, for drilling the Pecos River Deep Unit #5, we plan to plug and abandon this well by setting 100' plugs as follows:

950-850' 35 sx.

500-400' 35 sx.

20' surface plug with regulation marker.

18. I hereby certify that the foregoing is true and correct

SIGNED M. L. ArmstrongTITLE AgentDATE 9-20-67

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

APPROVED  
SEP 21 1967  
R. L. LEWIS  
ACTING DISTRICT ENGINEER

\*See Instructions on Reverse Side

RECEIVED  
SEP 21 1967  
U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO