

John W. West

Professional Engineer and Land Surveyor

412 N. Dal Paso Phone 270

Hobbs, New Mexico

June 19, 1954

Stanolind Oil & Gas Company
Box 68
Hobbs, New Mexico

Gentlemen:

June 18, 1954 a survey was made to stake your State
AI Lease Well No. 1, at a point 1650' from the north and
1650' from the east lines of Sec. 3, Twp. 19 South, Range
28 East, N.M.P.M., Eddy County, New Mexico.

The U.S.G.I.O. markers at the northeast and southeast
corners of the northeast quarter of Sec. 3 were located
and flags set at each. The transit was wiggled in on a
hill between the two markers and the survey was started
at the northeast corner. We chained south along the
section line 1650', thence west 1650' to the location.
We then checked back to the east quarter corner marker
a distance of 1928.5' on a bearing of S53°47'W. This
was not the proper closure so we checked again and found
the distance between the two U.S.G.I.O. markers to be
2650'. With this extra long half section our closure
was alright. The location is 1650' south of the north
line of the section and 1000' north of the south half
of the section.

I hereby certify that the foregoing survey was made
in the field by me and that the same is true and correct
to the best of my knowledge and belief.

Respectfully submitted,

John W. West
John W. West

1997, 1998, 1999.

James Wilson

[illegible]

1. The first step is to identify the problem or goal. This involves understanding the current situation, identifying the problem, and setting a clear goal.

James W. Smith