

NEW MEXICO STATE LAND OFFICE
SANTA FE, NEW MEXICO
DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

.....**Artesia**....., N. Mex. **Jan. 10th.** 19**34**

Mr. **E. H. Wells**
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon Well
No. **67** in **NW 1** of Sec. **10** Twp. **19**, Rge. **28**,
N. M. P. M., **Artesia** Oil Field, **Eddy** County.
We plan to commence work on **January 12th.**, 19**34**.

The reasons for wishing to abandon the well are as follows:

Dry Hole

The present condition of the well is as follows:

Total Depth 2154 feet.
No oil or water
315 feet 10" pipe set to shut off cave.

The work which we propose to do in abandoning the well is as follows:

Fill hole with mud from 2154 feet to 1985 ft. Cement five sacks.
Fill hole with mud to bottom of ten inch. Pull 10" pipe and fill
hole to surface. Place regulation marker.

DUPLICATE

Sincerely yours,

Approved 1-22 19**34**

Except as follows:

F. W. & Y. OIL COMPANY

Company or Operator.

By N. H. Gladys

Position **Assistant Secretary**

Send communications regarding this well to

Name **F. W. & Y. Oil Company**

Address **Artesia, New Mexico**

[Signature]
State Geologist or Oil and Gas Inspector.