

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

OCT 17 1983

O. C. D.

ARTESIA OFFICE

5a. Indicate Type of Lease

State ☒Fm ☐

5. State Oil &amp; Gas Lease No.

648

SUNDY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injector	7. Unit Agreement Name
2. Name of Operator DEPCO, Inc.	8. Farm or Lease Name State 648 Ac. 811
3. Address of Operator 800 Central, Odessa, TX 79761	9. Well No. 67
4. Location of Well UNIT LETTER F 2147 FEET FROM THE North LINE AND 1521 FEET FROM THE West LINE, SECTION 10 TOWNSHIP 19-S RANGE 28-E NMPM.	10. Field and Pool, or Wildcat Artesia, Q.G. SA
15. Elevation (Show whether DF, RT, GR, etc.) 3538 G.R.	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-23-83: Set CIBP @ 1945'.

9-27-83: Spotted 15 sx cement plug on top of CIBP. Loaded hole to 625' w/9# mud laden fluid. Spotted 35 sx cement plug. Pulled tbq. and pumped 75 sx cement. Did not circulate. Over-displaced with water.

9-28-83: Pumped 75 sxs cement. Did not circulate, over-displaced.

9-29-83: Pumped 100 gals. Flochek followed w/50 sxs cement, pumped 100 gals. Flochek followed with 50 sxs cement. Pumped 100 gals, Flochek followed with 50 sxs 50/50 Calseal. Over-displaced. Tied onto surface pipe and pumped 70 sxs cement. Had good returns. Left 4 1/2" and 7" csg full of cement

Installed dry hole marker and cleaned location.

Mr. Mike Williams with the Oil Commission witnessed the plugging procedure.

Post ID-2  
10-21-83  
P+H

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Leon Standard TITLE Field Engineer DATE 10-14-83

APPROVED BY Darryl Brooks TITLE Geologist DATE 2-13-84

CONDITIONS OF APPROVAL, IF ANY: