

3-31-81

This P & A wasn't reported on
the ID-2 reports because it was
Re-entered to be re-plugged
properly, as a result of an
offset Waterflood project.

Betty

6-26-81 ID-2 sent to R. S. S. S. S.