

NO. OF COPIES RECEIVED	4
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>00-784</b>

**SUNDY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> 2. Name of Operator <b>SUN OIL CO. - DX DIVISION</b> 3. Address of Operator <b>Box 128, Hobbs, New Mexico</b> 4. Location of Well UNIT LETTER <b>D</b> , <b>660</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>13</b> TOWNSHIP <b>19</b> RANGE <b>28</b> NMPM. 15. Elevation (Show whether DF, RT, GR, etc.) <b>3399' DF</b>	7. Unit Agreement Name 8. Farm or Lease Name <b>New Mexico State</b> 9. Well No. <b>2</b> 10. Field and Pool, or Wildcat <b>E. Millman Queen, Obg.</b> 12. County <b>Eddy</b>
---	---

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull tbg, rods & pump, perf 2 holes per ft as follows:  
2046-48, 2050-52, 2053-57, 2063-71, 2078-85, 2090-2102.
2. Acidize w/2000 gal BDA & frac w/30,000 gal ref oil & 90,000# sand.
3. Put well back on pump & recovered frac oil. Potentialled for 46 BO & 24 BW in 24 hours, OOR 1925.

RECEIVED

JAN 25 1965

O. C. C.  
ARTESIA, OFFICE

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B.F. Brawley TITLE District Engineer DATE 1-22-65

APPROVED BY M.L. Armstrong TITLE CH. AND GEN. INSPECTOR DATE JAN 22 1965

CONDITIONS OF APPROVAL, IF ANY: