OISTERNATION	IL CONSERVA		Form Collin Revised 45 3 22
SANTA FE FILE U.S.O.S. LAND OFFICE OPPRATOR	SANTA FE, NEW	00-	State X Leave 1 on 1 o
SUN (DO NOT USE THIS FORM FOR USE TAPPLE	7. Unit Agreement Nan.e		
2. Name of Operator DEPCO. Inc. 3. Address of Operator	OTMER. WIW		8. Farm or Leane Name State 648 9. Well No.
800 Central Odess 1. Location of Well West	1980 FEET FROM THE South		143 10. Field and Pool, or Wildcat East Millman, Q, GBR, SA.
THE LINE, SE	15. Elevation (Show whether 3427 DF ck Appropriate Box To Indicate I	· DF, RT, GR, etc.)	12. County Eddy Or Other Data
NOTICE OF	F INTENTION TO: PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK COMMENCE DRILLING OPNS. CASING TEST AND CEMENT JQB	UENT REPORT OF: ALTERING CASING PLUG AND ABANDONMENT
other		OTHER	denhead inspection X
to surface fro	om annulus.	radenhead. Connections	s with valves were installed
Inspected by I	Mr. B.W. Weaver 8-20-80.		
18. I hereby certify that the inform	ation above is true and complete to the bes	t of my knowledge and belief.	

OIL AND GAS INSPECTOR

bul 1

1200