

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

NOV 20 1974

O. C. C.  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>	
5. State Oil & Gas Lease No. 648	
7. Unit Agreement Name	
8. Farm or Lease Name State 648	
9. Well No. 152	
10. Field and Pool, or Wildcat E. Millman Q-G-SA	
12. County Eddy	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input checked="" type="checkbox"/> Water Injection Well
2. Name of Operator DEPCO, Inc. /
3. Address of Operator 800 Central, Odessa, Texas 79761
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM East THE LINE, SECTION 22 TOWNSHIP 19s RANGE 28e NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)  
3421 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	Well shut-in <input checked="" type="checkbox"/>
OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well shut-in October, 1969, due to poor performance from offset producers.  
Well located in an active waterflood project; therefore, need to maintain well bore for possible return to injection status.  
Presently unable to estimate date of any future work.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Chief Clerk DATE 11-18-74

APPROVED BY [Signature] TITLE OIL AND G'S INSPECTOR DATE NOV 25 1974

CONDITIONS OF APPROVAL, IF ANY: Edwards 10-1-74