

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
30-015-02290

Indicate Type of Lease  
STATE ☒ FEE ☐

State Oil & Gas Lease No.

Lease Name or Unit Agreement Name  
East Millman Unit

Well No.  
162

Pool name or Wildcat  
Millman, YT-7R, East (46555)

Well Location  
Unit Letter H 1650 Feet From The North Line and 660 Feet From The East Line  
Section 22 Township 19S Range 28E NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3387 GR

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER

Name of Operator  
SDX Resources, Inc.

Address of Operator  
PO Box 5061, Midland, TX 79704

Well Location  
Unit Letter H 1650 Feet From The North Line and 660 Feet From The East Line  
Section 22 Township 19S Range 28E NMPM Eddy County

Elevation (Show whether DF, RKB, RT, GR, etc.)  
3387 GR

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

#### Casing Condition:

10-3/4" @ 470' w/50 sx. TOC calc @ 50'  
8-5/8" @ 1372' w/50 sx. TOC calc @ 900'  
4-1/2" @ 2290' w/250 sx. TOC calc @ 900'  
Perfs: 1740' - 2208'

#### Propose to P&A as follows:

100' Plug 2208 to 2308'  
Set CIBP @ 1660'. Spot 10 sx plug & top of CIBP. Circ mud laden fl. Cut & pull 4-1/2" csg from 900' if possible. Cut & pull 8-5/8" from 900' if possible. Spot 35 sx plug 950' - 850'. Spot 50 sx plug 520' - 420'. Spot 10 sx surf plug. Install marker & clean location.

TA9

TA9

60'

Give OCU 24 HRS notice prior to any work

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Atwater TITLE Regulatory Tech DATE 08-25-01

TYPE OR PRINT NAME Bonnie Atwater TELEPHONE NO. 915/685-1761

(This space for State Use)

APPROVED BY [Signature] TITLE Field Rep ID DATE 8-30-01

CONDITIONS OF APPROVAL, IF ANY: