

www.

5/8/74

Inspected well. No pump jack or flow
line on well. Bradenhead covered
with dirt could not locate well.

M.S.