

STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION ARTESIA DISTRICT OFFICE

June 5, 1986

P.O. DRAWER DO ARTESIA, NEW MEXICO 88210 (505) 748-1283

Herman J. Ledbetter P.O. Box 5879 Abilene, Texas 79605

Mr. Ledbetter,

Before we can approve pumping cement down the production casing we need to know where the holes are in the casing.

It is our policy to find the top of the cement on the production casing and to make sure we have cement up to the base of the salt before we start any repair work above the salt section.

I have been unable to contact you by telephone. If you could call me I am sure we could work out a proceure on repairing your wells.

Sincerely,

Mike Williams

Oil & Gas Inspector

mik William

MW;br