

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
SANTA FE	1
FILE	1-
U.S.G.S.	
LAND OFFICE	
OPERATOR	4

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. B-8096	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator John A. Yates		8. Farm or Lease Name Elizabeth Dundas
3. Address of Operator 323 Carper Building, Artesia, New Mexico.		9. Well No. 2
4. Location of Well UNIT LETTER N, 990 FEET FROM THE South LINE AND 1650 FEET FROM West THE LINE, SECTION 7 TOWNSHIP 19 South RANGE 29 East NMPM.		10. Field and Pool, or Wildcat East Millman, Q-Gr
15. Elevation (Show whether DF, RT, GR, etc.) 3382 DF		12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

In accordance with conversation with W. A. Gressett, plan to plug and abandon well as follows:

Will recover as much 4½" casing as possible. Will fill hole with heavy mud and spot cement plug across perforations at 2101 to 2080 feet.

When it is determined where the stub of 4½" casing is located, will call the office of the Oil Conservation Commission for instructions to complete plugging.

RECEIVED

DEC 21 1966

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nola Crader TITLE Bookkeeper DATE 12-21-66

APPROVED BY W. A. Gressett TITLE OIL AND GAS INSPECTOR DATE DEC 21 1966

CONDITIONS OF APPROVAL, IF ANY: