Form 3160-5 (August 1999)

UNIT **STATES**

Set 20 sx cmt plug @ surface.

Plugging operations began 12/11/00. Plugging operations complete 12/14/00. N.M. Oil Cons. Division 811 S. 1st Str€

FORM APPROVED

Artesia, NM 88210-2834 Expires November 30, 2000 DEPARTMEN'I OF THE INTERIOR **BUREAU OF LAND MANAGEMENT** 5. Lease Serial No. LC029389A SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well 8. Well Name and No. 🔀 Oil Well 🔲 Gas Well 🔲 Other Edwards Federal #1 Name of Operator 9. API Well No. Kaiser-Francis Oil Company 30-015-05499 3b. Phone No. (include area code) 3a. Address 10. Field and Pool, or Exploratory Area 918-491-4314 P. O. Box 21468, Tulsa, OK 74121-1468 Shugart Yates 7 Rivers Queen 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, State Grayburg 990' FSL & 2310' FEL of Sec. 9-18S-31E Eddy/NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION ■ Water Shut-Off Production (Start/Resume) Deepen ☐ Acidize Well Integrity ■ Reclamation ☐ Notice of Intent Fracture Treat Alter Casing Other **New Construction** Recomplete Casing Repair Subsequent Report Temporarily Abandon Plug and Abandon Change Plans ■ Water Disposal Final Abandonment Notice Plug Back Convert to Injection Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Dumped 3 sxs cmt on top of CIBP @ 3127'. Calculated TOC @ 3082'. 1. Set 25 sx cmt plug from 2000'-1750'. Located free-point on 5½" casing. Cut & pulled 877' (Approved by Jim Amos). Set 100 sx cmt plug from 1130'-756'. Tagged. Perf'd 8 5/8" casing @ 200' & set cmt retainer @ 96'. 19e' per Ins Pumped 70 sxs cmt through retainer & circ'd to surface.

			23/4
14. I hereby centify that the foregoing is true and correct Name (Printed/Typed) Charlotte Van Valkenburg	Title	Technical	Coordinator
Signature C. an alkerbeng	Date		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by (ORIG. SGD.) JOE G. LARA		Title	Date 2/13/2001
Conditions of approval, if any, are attached. Approval of this notice does not warn certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	rant or t lease	Office CF	-C