NO. OF COPIES RECEIVED			
DISTRIBUTION	1	CONSERVATION COMMISSION	Form C-104
SANTA FE	<u></u>	FOR ALLOWABLE	Supersedes Old C-104 and C-1 Effective 1-1-65
U.S.G.S.	AUTUODIZATION TO TO	AND AND FATUREL	VED
LAND OFFICE	AUTHORIZATION TO TR	ANSPORT OIL AND NATURAL	GAS
TRANSPORTER OIL		JUL 3	1972
GAS	$\frac{1}{2}$	305 >	1372
OPERATOR	4	O. C.	C .
Operator Operator		ARTESIA, C	
Penasco Corporation	a		
Address	a, New Mexico 88210		
Reason(s) for filing (Check proper box	-, .,	Other (Please explain)	
New Well	Change in Transporter of:	Office (Freeze explain)	1
Recompletion	Oil Dry G	Gas Change well i	name
Change in Ownership	Casinghead Gas Conde	ensate 📑	Les Land
If change of ownership give name			
and address of previous owner			
DESCRIPTION OF WELL AND	LEASE		
Lease Name	Well No. Pool Name, Including I	1	20000
Penasco Shugart Unit	N-1 Shugart Y. SR	R.Q.G. State, Feder	alorFee Fed. LC 029389c
Location M 660	South	660	west
Unit Letter 11 ; 000	Feet From The South Li	ine and ODU Feet From	The West
Line of Section 9 To	waship 185 Range	31E , NMPM, Eddy	County
DESIGNATION OF TRANSPOR' Name of Authorized Transporter of Oil	TER OF OIL AND NATURAL G	AS Address (Give address to which appro	oved conv of this form is to be sent)
Texas-New Mexico Pipe	• •		d, Texas
Name of Authorized Transporter of Car		Address (Give address to which appro	
	_		
l			
If well produces oil or liquids,	Unit Sec. Twp. Rge.		nen
give location of tanks.	M 9 185 31E	No	nen •
give location of tanks. If this production is commingled wi		No	nen •
give location of tanks. If this production is commingled wi COMPLETION DATA	th that from any other lease or pool,	No	
give location of tanks. If this production is commingled wi	th that from any other lease or pool, on - (X)	No No No Now Well Workover Deepen	Plug Back Same Restv. Diff. Rest
give location of tanks. If this production is commingled wi COMPLETION DATA	th that from any other lease or pool,	No No give commingling order number:	
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic Date Spudded	th that from any other lease or pool, on - (X) Oil Well Gas Well Date Compl. Ready to Prod.	No No No Now Well Workover Deepen	Plug Back Same Resty. Diff. Rest
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic	th that from any other lease or pool, on - (X)	No No give commingling order number: New Well Workover Deepen Total Depth	Plug Back Same Resty. Diff. Rest
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic Date Spudded	th that from any other lease or pool, on - (X) Oil Well Gas Well Date Compl. Ready to Prod.	No No give commingling order number: New Well Workover Deepen Total Depth	Plug Back Same Resty. Diff. Rest
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic Date Spudded Elevations (DF, RKB, RT, GR, etc.)	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation	No , give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay	P.B.T.D. Tubing Depth
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations	th that from any other lease or pool, on - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	No , give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic Date Spudded Elevations (DF, RKB, RT, GR, etc.)	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation	No , give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay	P.B.T.D. Tubing Depth
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations	th that from any other lease or pool, on - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	No , give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations	th that from any other lease or pool, on - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN	No , give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled wi COMPLETION DATA Designate Type of Completic Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE	No , give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be	No , give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOOLL WELL	th that from any other lease or pool, Oil Well Gas Well On - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this december)	No , give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be	No , give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOOLL WELL	th that from any other lease or pool, Oil Well Gas Well On - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this december)	No , give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOR OIL WELL Date First New Oil Run To Tanks	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d	No , give commingling order number: New Well Workover Deepen	P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allo ift, etc.) Choke Size
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOR OIL WELL Date First New Oil Run To Tanks	th that from any other lease or pool, on - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d	NO , give commingling order number: New Well Workover Deepen	P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowift, etc.)
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOOIL WELL Date First New Oil Run To Tanks Length of Test	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d	No , give commingling order number: New Well Workover Deepen	P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowift, etc.) Choke Size
give location of tanks. If this production is commingled wich COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOOIL, WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d	No , give commingling order number: New Well Workover Deepen	P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowift, etc.) Choke Size
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOOIL WELL Date First New Oil Run To Tanks Length of Test	th that from any other lease or pool, on - (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d	No , give commingling order number: New Well Workover Deepen	P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowift, etc.) Choke Size
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL	th that from any other lease or pool, Oil Well Gas Well On - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d Date of Test Tubing Pressure Oil-Bbis.	No give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay ID CEMENTING RECORD DEPTH SET after recovery of total volume of load oil lepth or be for full 24 hours) Producing Method (Flow, pump, gas left) Casing Pressure Water-Bbls.	P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowift, etc.) Choke Size Gas-MCF
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL	th that from any other lease or pool, Oil Well Gas Well On - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d Date of Test Tubing Pressure Oil-Bbis.	No give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay ID CEMENTING RECORD DEPTH SET after recovery of total volume of load oil lepth or be for full 24 hours) Producing Method (Flow, pump, gas left) Casing Pressure Water-Bbls.	P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allowift, etc.) Choke Size Gas-MCF
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST Formula of Test New Oil Run To Tanks Length of Test Actual Prod. During Teet GAS WELL Actual Prod. Test-MCF/D	th that from any other lease or pool, on — (X) Date Compl. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d Date of Test Tubing Pressure Oil-Bbis.	No , give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allo ift, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST Formula of Test New Oil Run To Tanks Length of Test Actual Prod. During Teet GAS WELL Actual Prod. Test-MCF/D	th that from any other lease or pool, on - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d Date of Test Tubing Pressure Oil-Bbis. Length of Test Tubing Pressure (Shut-in)	No , give commingling order number: New Well Workover Deepen	Plug Back Same Res'v. Diff. Res' P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top allo ift, etc.) Choke Size Gas-MCF Gravity of Condensate Choke Size
give location of tanks. If this production is commingled with COMPLETION DATA Designate Type of Completion Date Spudded Elevations (DF, RKB, RT, GR, etc.) Perforations HOLE SIZE TEST DATA AND REQUEST FOOIL WELL Date First New Oil Run To Tanks Length of Test Actual Prod. During Test GAS WELL Actual Prod. Test-MCF/D Testing Method (pitot, back pr.) CERTIFICATE OF COMPLIANCE	th that from any other lease or pool, on - (X) Date Compi. Ready to Prod. Name of Producing Formation TUBING, CASING, AN CASING & TUBING SIZE OR ALLOWABLE (Test must be able for this d Date of Test Tubing Pressure Oil-Bbis. Length of Test Tubing Pressure (Shut-in)	No give commingling order number: New Well Workover Deepen Total Depth Top Oil/Gas Pay DEPTH SET after recovery of total volume of load oil lepth or be for full 24 hours) Producing Method (Flow, pump, gas lepth or be for full 24 hours) Casing Pressure Water-Bbls. Bbls. Condensate/MMCF Casing Pressure (Shut-in) OIL CONSERVA	Plug Back Same Resiv. Diff. Resive P.B.T.D. Tubing Depth Depth Casing Shoe SACKS CEMENT and must be equal to or exceed top alice ift, etc.) Choke Size Gas-MCF

Agent

July 1,

(Title)

1972 (Date) This form is to be filed in compliance with RULE 1104.

VIE AND GAS INGPESIGH

TITLE _

If this is a request for allowable for a newly drilled or deepened well, this form must be accompanied by a tabulation of the deviation tests taken on the well in accordance with RULE 111.

All sections of this form must be filled out completely for allowable on new and recompleted wells.

Fill out only Sections I. II. III, and VI for changes of owner, well name or number, or transporter, or other such change of condition. Separate Forms C-104 must be filed for each pool in multiply