

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TR (Other instructi
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-062052

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Shugart "B"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Shugart Queen

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 11-T18S-R31E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Injection Well

2. NAME OF OPERATOR

William A. & Edward R. Hudson

3. ADDRESS OF OPERATOR

P.O. Box 9, Maljamar, New Mexico 88264

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

SW 1/4, SW 1/4
Sec. 11-T18S-R31E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3723.6 GL

O. C. D.
ARTESIA, OFFICE

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

We propose to permanently plug and abandon this well as follows:

Set a bridge plug at 3250', spot 50' cement on top of plug, load hole with salt gel mud, spot 100' cement from 2000' to 1900', perf. 5-1/2" casing at 750', set a cement retainer in 5-1/2" casing at 710', circulate cement to surface through perforations at 750', fill hole with fresh water to the surface, spot 150' cement on top of retainer, spot 50' cement at the surface.

→ S.J. Shaw as per D. Howard.

Clean location and reseed in accordance with BLM stipulations.

Notify BLM at 887-6344 prior to commencing P & A operations.

Notify NMOCDC at 748-1283 prior to commencing P & A operations.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Prod. Supt.

DATE 7/14/89

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

FOR:

TITLE

DATE

8-1-89

*See Instructions on Reverse Side

WILLIAM A. & EDWARD R. HUDSON
Shugart B No. 1

SKETCH

