

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	
FILE	1
U.S.G.S.	1
LAND OFFICE	
OPERATOR	1

**RECEIVED**  
NEW MEXICO OIL CONSERVATION COMMISSION

JAN 17 1979

**O. C. C.**  
ARTESIA, OFFICE

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

**Federal**

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 14-08-0018862
7. Unit Agreement Name
8. Farm or Lease Name Taylor Unit
9. Well No. 15
10. Field and Pool, or Wildcat Shugart (Y,SR,Q,G)
12. County Eddy

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <b>WIW</b>
2. Name of Operator Shenandoah Oil Corporation ✓
3. Address of Operator P. O. Box 4534 - Odessa, Texas 79760
4. Location of Well UNIT LETTER <b>F</b> 1980 FEET FROM THE <b>N</b> LINE AND 1980 FEET FROM THE <b>W</b> LINE, SECTION <b>13</b> TOWNSHIP <b>18S</b> RANGE <b>31E</b> NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3734 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <b>Bradenhead Tie In</b> <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

No Bradenhead - Open 2" pipe from top of casing clamp to surface with 2" ell exposed.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>C.M. Dawney Jr.</i></u>	TITLE <u>Division Manager</u>	DATE <u>January 15, 1979</u>
	<u>West Texas-New Mexico</u>	
APPROVED BY <u><i>Mik. Walker</i></u>	TITLE <u><b>OIL AND GAS INSPECTOR</b></u>	DATE <u>JAN 16 1979</u>
CONDITIONS OF APPROVAL, IF ANY:		