

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPI (TE)
(Other instruction: re
verse side)

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

dst

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐ Water Injection
2. NAME OF OPERATOR William A. & Edward R. Hudson
3. ADDRESS OF OPERATOR P.O. Box 9, Maljamar, New Mexico 88254-1 '89
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface
1980' from North and East lines,
Sec. 15-18S-31E
14. PERMIT NO.
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
3698' DF
16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:
TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐
FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐
SHOOT OR ACIDIZE ☐ ABANDON* ☐
REPAIR WELL ☐ CHANGE PLANE ☐
(Other) ☐
SUBSEQUENT REPORT OF:
WATER SHUT-OFF ☐ REPAIRING WELL ☐
FRACTURE TREATMENT ☐ ALTERING CASING ☐
SHOOTING OR ACIDIZING ☐ ABANDONMENT* ☒
(Other) ☐
(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
Nov. 7, 1989 this well was plugged and abandoned using the following procedure:
Set a "cast iron" bridge plug in 5-1/2" casing at 3265', spotted 50' (5sk.) cement on top of plug, loaded hole w/salt gel mud, spotted cement plug from 1842' to 1742', (10 sks.) perforated 5-1/2" casing at 800' w/4 shots, set cement retainer in 5-1/2" casing at 750', loaded hole w/fresh water, circulated cement through perforations to the surface. (150 sks.), spotted 150' cement on top of cement retainer, (15 sks.) spotted 60' cement at the surface. (6 sks.) used 186 sks. class "C" cement to plug well, installed a dry hole marker w/all well data.
Nov. 8, 1989--Cleaned location of all debris.
Nov. 18, 1989, the location and road was ripped to a depth of 12" and an earthen barricade was installed to discourage vehicular travel.
Nov. 21, 1989, the area was re-seeded w/5# alkali sacaton and 20# four wing saltbrush..The area is ready for final inspection and the surface restoration work has been completed.
18. I hereby certify that the foregoing is true and correct
SIGNED William A. Hudson TITLE Prod. Supt. DATE 11/27/89
(This space for Federal or State office use)
APPROVED BY Orig. Signed by Adam TITLE PETROLEUM ENGINEER DATE 11-30-89
CONDITIONS OF APPROVAL, IF ANY:
Approved in accordance with BLM 5003.
Leasing will be continued until surface restoration is completed.
*See Instructions on Reverse Side.
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.