## STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

we er teries actives	3	
DISTRIBUTION	Ĭ	
SANTA FE		i
FILE	1	
U.8.0.8.	1	
LAND OFFICE		
<u> </u>	1	

Marks & Garner Production Company

MELL [

2. Name of Operator

CO 87501 2 1979

ARTESIA, OFFICE

Form C-103 Revised 10-1-78

	3	OIL CONSERVATION DIVI
DISTRIBUTION		P. O. BOX-2088
SANTA FE		SANTA FE, NEW MEXICO 87
FILE	1/	FFB 1 2 19
U.S.O.S.	/	PED 1 & 10
LAND OFFICE		
OPERATOR		O. C. G.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PERSONS TO DRILL ON TO DEEPEN ON PLUG BACK TO A DIFFERENT RESERVOIR.

USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

Water Injection

Sa.	Indicate	Type o	d Leise	,	
	State [	Fede	eral	Fee	
3.	Sigle OI	& Gas	Lease	No.	
<u></u>	G-02	5778 (	(a)		
X-4-	$\tau\tau\tau\tau$	TTTT	1111	777	1771

N. Shugart Queen Unit

8. Farm or Lease Name

3. Address of Operat	or	•				5, WELL 140.
P. O. Box	763, Ho	bbs, New Mex	ico 88240			7
4. Location of Weil						10. Field and Pool, or Wildcat
	L	2310	FEET FROM THE South	330	FELT FROM	Shugart
			TOWNSHIP 18S			
			15, Elevation (Show whether <b>3644</b>	DF, RT, GR, etc.)		18. County Eddy
16.	C	heck Appropria	te Box To Indicate N	ature of Notice,	Report or Oth	er Data
	NOTICE	OF INTENTION	N TO:		SUBSEQUENT	REPORT OF:
PERFORM REMEDIAL TEMPORARILY ABAND PULL OR ALTER CASI	ON		PLUG AND ABANDON	REMEDIAL WORK  COMMENCE DRILLING C  CASING TEST AND CEM  OTHERCAS	ENT JQB	ALTERING CASING  PLUG AND ABANDONMENT

Dug out around bradenhead & installed valve and connection for pressure gauge. 1/31/79 Well inspected and approved by James Brasfield, USGS.

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

Agent TITLE Agent	DATE 2/9/79	1 3 1979
-------------------	-------------	----------