| GEOL ICAL SURVEN MO. C. C. S. WELL STATUS REPORT | | Section Township Hange 26 18S 31E | | | |
|---|---------------------------------------|--------------------------------------|-----------------|-------------|--|
| | | Footoge La | ocation of Well | : S | |
| (To be submitted in quintuplicate on all inactive wells) | | 330 | _ leet from | W | line line |
| Tom Boyd Drilling Co., Inc. Petroleum Building - Tower Suite, Roswell, NM 88201 | | Pool Sl | hugart | | |
| WELL NO. AND LEADE NAMELEAGE NO1 Hinkle B-26LC 02 | ь. 9392 (b) | Eddy | | BTATE NM | |
| 1. When Was Well Shut-in or Last Produced? Mid 1973 RECEIVED | | | | | |
| 2. <u>Type Well</u> X Oil Well Gas Well X Temp. Abd. We | 11 | 2 4 1971 C. C. | - | | • • • • • • • • • • • • • • • • • • • |
| 3. <u>Producing Capability</u> 0 BOPD MCFGPD | | A, DEELC | E | | |
| BWPD 30 Date Last | TestedMid | 1973 | | | |
| 4. Is Well Considered Capable of Production in Paying Qu | | Yes | |) | |
| 5. If Capable of Producing in Paying Quantities, Give Re | asons For Not P | REC | EHVE | D | |
| | | Nov | 22 1976 | | |
| · · · · · · · · · · · · · · · · · · · | l | | OGICAL SUR | | |
| 6. If Not Capable of Producing in Paying Quantities, Give Reasons For Not Plugging Well At This Time. Once Honeysuckle has completed drilling in the SE/4 of Section 26, there will either be a unit or water flood project installed to cover the S/2 of Sec. 26 and SW/4 Sec.25. This well will be needed as a producer using #5 as an injector. | | | | | |
| 7. What Are Future Plans For Operating Well (Include Esti We plan on working over the Hink | • | Mia 10 | 77 | | |
| , , , | , , , , , , , , , , , , , , , , , , , | • | `` | | |
| I hereby certify that the foregoing is true and correct SIGNED | ent p | ATB | 11/19/7 | 6 | . <u></u> |
| (This space for Federal or State office use) APPROVED BY Jok J. Land TITLE ACTING DISTRICT CONDITIONS OF APPROVAL, IF ANY: | ENGINEER | ATB NO | y 2 3 1976 | | |
| | | | | | |