

|                        |   |
|------------------------|---|
| NO. OF COPIES RECEIVED |   |
| DISTRIBUTION           |   |
| SANITARY               | 1 |
| FILE                   | 1 |
| U.S.G.S.               |   |
| LAND OFFICE            |   |
| OPERATOR               | 1 |

# NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED BY  
OCT 25 1985  
O. C. D.

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☒ Fee ☐  
5. State Oil & Gas Lease No.  
E-10001

**SUNDARY NOTICES AND OPERATIONS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR RE-DRILL OR RE-LOCATE A DIFFERENT RESERVOIR.  
USE APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER  
2. Name of Operator  
Southland Royalty Company  
3. Address of Operator  
21 Desta Drive, Midland, Texas 79705  
4. Location of Well  
UNIT LETTER A 330 FEET FROM THE North LINE AND 990 FEET FROM  
THE East LINE, SECTION 32 TOWNSHIP 18S RANGE 31E NMPH.  
15. Elevation (Show whether DF, RT, GR, etc.)  
3603' DF

7. Unit Agreement Name  
8. Form of Lease Name  
New Mexico "Y" State  
9. Well No.  
2  
10. Field and Pool, or Wildcat  
Shugart (Y, SR, Q, G)  
12. County  
Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

| NOTICE OF INTENTION TO:                        |                                                      | SUBSEQUENT REPORT OF:                               |                                               |
|------------------------------------------------|------------------------------------------------------|-----------------------------------------------------|-----------------------------------------------|
| PERFORM REMEDIAL WORK <input type="checkbox"/> | PLUG AND ABANDON <input checked="" type="checkbox"/> | REMEDIAL WORK <input type="checkbox"/>              | ALTERING CASING <input type="checkbox"/>      |
| TEMPORARILY ABANDON <input type="checkbox"/>   | CHANGE PLANS <input type="checkbox"/>                | COMMENCE DRILLING OPNS. <input type="checkbox"/>    | PLUG AND ABANDONMENT <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/>  | OTHER <input type="checkbox"/>                       | CASING TEST AND CEMENT JOB <input type="checkbox"/> |                                               |
|                                                |                                                      | OTHER <input type="checkbox"/>                      |                                               |

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify NMOCD in Artesia prior to setting plugs.

1. MIRUPU. POH w/rods & pmp, if any & RDP.
2. RU pump truck & establish PI rate dwn tbg. Check csg for communication.
3. Mix a 15<sup>25</sup> sx cmt plug & displace to 2000' (plug 2600-2000') w/10 ppg mud.
4. RIH w/CRC WL & perf @ 850'.
5. Est PI rate dwn tbg & check for communication to annulus. Circ hole w/+ 230 sx cmt.
6. Weld on marker & clean the location.

The above procedure was discussed with Larry Brooks NMOCD in Artesia.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Stark TITLE Operations Engineer DATE 10/22/85

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE OCT 24 1985

CONDITIONS OF APPROVAL, IF ANY: