

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY Artesia, NM 86420

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐  
2. NAME OF OPERATOR  
Point Petroleum Corporation ✓  
3. ADDRESS OF OPERATOR  
P. O. Box 3805, Midland, Texas 79702  
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface 2310 FSL and FWL  
Section 5, Township 19 South, Range 31 East  
NE/4 of NE/4 of SW/4 Unit K

14. PERMIT NO.  
15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
3561

RECEIVED BY  
MAR 28 1986  
O. C. D.  
FARM OR LEASE ARTESIA, O.C.D.  
Featherstone Federal  
8. WELL NO.  
1  
10. FIELD AND POOL, OR WILDCAT  
Shugart  
11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA  
5-19S-31E

12. COUNTY OR PARISH  
Eddy  
13. STATE  
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐  
FRACTURE TREAT ☐  
SHOOT OR ACIDIZE ☐  
REPAIR WELL ☐  
(Other) ☐  
PULL OR ALTER CASING ☐  
MULTIPLE COMPLETE ☐  
ABANDON\* ☐  
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐  
FRACTURE TREATMENT ☒  
SHOOTING OR ACIDIZING ☒  
(Other) ☐  
REPAIRING WELL ☐  
ALTERING CASING ☐  
ABANDONMENT\* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 1/10/86 Run cement bond log and set cast iron bridge plug at 3415'.  
Dump 34 feet of cement on top of plug.
- 1/13/86 Perforate 3228-36, 3238-45, 3248-52 38 holes. Acidize zone  
with 2500 gallons of 15% NEFE acid.
- 1/14/86 Swab acid back.
- 1/15/86 Frac well with 30,000 gallons of gelled 2% KCL water with  
2000# of 100 mesh, 37,000# of 20/40 and 18,500# of 12/40  
sand.
- 1/17/86 Run 101 jts. of 2 3/8" tubing to 3200' and hang well on the  
pump.

ACCEPTED FOR RECORD

MAR 24 1986

CARLSBAD, N.M., MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED Charles Morgan TITLE Agent

DATE 3/15/86

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE \_\_\_\_\_