

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

CONTACT RECEIVING  
OFFICE FOR NUM  
OF COPIES REQUIRED  
(Other instructions on re-  
verse side)

BLM Roswell District  
Modified Form No.  
NMD60-3160-4

457

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Marbob Energy Corporation		3a. Area Code & Phone No. 505-748-3303	
3. ADDRESS OF OPERATOR P. O. Drawer 217, Artesia, NM 88210		8. FARM OR LEASE NAME Tidewater Federal	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  Unit O: 990 FSL 1980 FEL		9. WELL NO. 1	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, OR, etc.) O. C. D.	
		10. FIELD AND POOL, OR WILDCAT Hackberry Yates SR, North	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19, T19S, R31E	
		12. COUNTY OR PARISH Eddy	
		13. STATE NM	

RECEIVED

SEP 30 1992

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANE <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

- 1) Spot 25 sacks cement at 2164' W.O.C. Tag at 2158'.
- 2) Respot 25 sacks cement at 2158' W.O.C. Tag at 1930'.
- 3) Load hole with mud.
- 4) Spot 25 sacks cement at 1840'.
- 5) Perforate 4-1/2" casing at 630' and bull head squeeze with 135 sacks cement to surface.  
Set P&A marker.

P&A in 8/28/92

Post IO-2  
10-9-92  
P&A

Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

18. I hereby certify that the foregoing is true and correct

SIGNED Robert Chan TITLE Supervisor

DATE 9/14/92

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_

DATE 9/28/92

\*See Instructions on Reverse Side